
CERTIFIED LAND CORNER RESTORATION


State of Wisconsin					
State of Wisconsin County of Forest	SS.				
I William B. Cochrane I found evidence of the North Township 36 North hereon; and that from this evid petuate the original location of	quarter Range 15 Eas ence I established a ne	t corner	of <u>Section</u> Fourth Principa	22 1 Meridian, a	s described
Description of original monumer	nt and accessories and	subsequent restors	tions:		
Surveyed in 1859 by Jam West corrected between Sugar, 12 inches, N21E, Hemlock, 12 inches, S71	Sections 15 and 22 3 links	, 40.20 chains	set $\frac{1}{4}$ section	n post.	
Description of corner evidence f	ound:			i.	
1 inch iron rod in a mo Sugar maple stump, N21E Hemlock stump, S71W, 3	, 3 links	decayed wood po	st lying nex	t to the in	ron rod.
t t					•
Description of monument and a	ccessories I established	l to perpetuate the	location of this	s corner:	
I replaced the iron rod 3 feet long, with an alm T36N, R15E, $\frac{1}{4}$, S15, S22 Blazed and scribed the Hemlock, 18 inches, N19 Sugar Maple, 6 inches, 1	uminum cap stamped, 1980, S-1107. following new bear W, 16.54 feet N53E, 17.62 feet		Sold in the Control of the Control o	ILLIAM B. OCHRANE S-1107 HILES, VISCONSIN	
	Resident witnesses	·		つかも 。	3.60
Sec. 22	Signature William	lam B. Coc B. Cochrane	Title L	and Survey	oř
	County Surveyo Surveyors Registrate	r, Registered Land Sution No. S-1107	rveyor, or other d DOCUMEN NO	VIT 11	3074
Corner monument restored Township 36 North Ran	Office of Regis I hereby certify the on the 9th No.	ter of Deeds It the within instru day of June Page No.	County of ment was filed 19.80 of County	in this office on the state of	for record led in Book

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

Quarter Corner to Section 15 22 T 36N, R 15E (Section/Quarter)



O = Corner monument restored.



Corner consists of a 2½" aluminum post with cap stamped for corner. Distances are to nails in the trees which are scribed "BT" and blazed. Bearings are magnetic.

16"MAPLE

Kim H Pritzlaff. Contractor for the USFS (Type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature

Date

History of original corner establishment, record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence, and what you found and how the monument was set.

In 1859 James McBride set a wood post at this corner location with the following scribed bearing trees:

N21°E 3 links Sugar S 71°W Hemlock 3 links

In 1980 Bill Cochrane found a 1" iron rod and decayed wood post and stumps of the original bearing trees. He set a 2½" aluminum post at this corner location and marked two bearing trees, a Hemlock and Sugar.

I found Cochrane's monument in good shape along with his two bearing trees, now a 20" Hemlock and a 10" Sugar. I blazed and scribed two more trees and set a steel sign post as noted below.

In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material, except wood other than bearing trees.) Also, show any material discrepancies between the corner restored or re-established and the location of any other previous corner location or occupation.

> 20" HEMLOCK 10" SUGAR MAPLE S 80° W REGISTER'S OFFICE / Forest County, Wis.

Received for record this 3 day of January A.D. 1992 at

9:30 o'clock .A.M. and recorded In Volberter RESTORATIONS