	U. S.	
State of Wisconsin ss.		
County of Forest		
I Gary L. Pisoni , do he certify that on the 30th of March , 19.94 , I evidence of the Northeast corner of Section 24 Township 36 North, I 16-17 East , Fourth Principal Mer as described hereon; and that from this evil established a new monument and access as described hereon to perpetuate the or location of this corner.	found found Range idian, dence sories	
Resident witnesses:		

= Corner monument restored.

History of original corner establishment:

Original Government Survey in 1857 by Artemas Curtis. North between Sections 24 and 19 at 80.00 chains, set Section post from which the following bear: Sugar, 12", S 38 W, 25 lks; Sugar, 18", N 47 W, 69 lks; Sugar, 15", N 61 E, 37 lks; Yellow Birch, 26", S 34 E, 30 lks.

In 1936 and 1937, Marinette County surveyors, F.P. Gould and B.F. Hammes found a hardwood post and 2" iron pipe and found the original bearing tree stumps; Replaced iron pipe with a 4"dia. iron post in concrete with a Marinette County brass cap from which the following bear: Elm 6" N 11 W 167.5 lks.

Description of corner evidence found:

Found the monument and assessories as described above: Steel sign post North 0.7 feet

Description of monument and accessories I established to perpetuate the original location of this corner.

Blazed and scribed the following new bearing trees: (Measurements taken to nail in side of tree)

Sugar Maple	7"	N 44°E	27.80 feet
Sugar Maple	7 "	s 34°E	12.45 feet
Sugar Maple	8"	s 38°W	12.19 feet
Sugar Maple	8 11	$^{\rm N}$ 40 $^{\rm O}$ W	18.81 feet
Steel sign pos	t	West	0.90 feet

Dated at	Iron	River	, MI	, Vs., this	26th	dav of	May	19
Signature	fory	21	Ryon	Title	Land	Surveyor	Regi	stration No.
Signature Title Land Surveyor Registration NoS-1634 (County Surveyor, Registered Land Surveyor, or other duly authorized official)								
Office of R	legister of	f Deed:	s, County of	tocest		/	, I hereby	certify that the within
instrument	t was filed	d in thi	is office for rec	ord on the	2014	day o	S. Maich	
Office of Register of Deeds, County of								
			Register of Deed	e)		****		

Jul Taleurez Deput

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

None

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

