


U. S. PUBLIC LAND SURVEY MONUMENT RECORD

INSTRUCTIONS: This record shall show the location of the corner and shall include all of the following nine elements (a through i).

(a) Identify the corner by reference to the U.S. public land survey system.

○ = Corner monument restored.

Corner of Townships 35-36 North, Ranges 16-17 East, Forest-Marinette Counties, Wisconsin.




(b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

Corner found marked by an iron pipe with a 4" Marinette County brass cap, as set by J. J. Jenkins in 1934-1935.

(c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.) Describe witness monuments.

(d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.

- 6/1969--Made new bearing trees:
- 1. Maple, 10", N.22°E., 35.45 feet
 - 2. Maple, 13", S.46°E., 32.07 feet
 - 3. Maple, 6", S.68°W., 11.34 feet
 - 4. Elm, 7", N.13°W., 31.43 feet
- 3/1984--Repainted above bearing trees and set following:
- 5. Steel Sign Post, North, 1.20 feet



REGISTER'S OFFICE }
Forest County, Wis. }
Received for record this...1st...day
of April...A. D., 1985 at
2:05...o'clock...P...M. and
recorded in Vol. CORNER RESTORATIONS
on page A-25
Paul Aschenbrenner
REGISTER

e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

None.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Found perpetuated location.


(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

No.

(i) I, Milo E. Stefan
(Type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Milo E. Stefan
Signature

12/31/84
Date



CERTIFIED LAND CORNER RESTORATION

State of Wisconsin

County of Forest

ss.

I Jean F. Resvick do hereby certify that on the 21st day of July, 1969, I found evidence of the Northeast Section corner of Section 1 Township 35 North, Range 16 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new ~~monument and~~ accessories as described hereon to perpetuate the ~~original~~ location of this corner:

Description of original monument and accessories and subsequent restorations:

Surveyed in 1859 by Artemas Curtis.

Set wood post.

Sugar 18, bears S12W, 15 lks.

Sugar 15, bears N54W, 26 lks.

Sugar 15, bears N40E, 35 lks.


Y. Birch 18, bears S70E, 32 lks.

Survey for Marinette County by J.J. Jenkins, Menominee County Surveyor, in Dec. 1934 and Jan. 1935 and recorded in Marinette County.

Set 4" iron post for the corner to sections 1, 6, 31, and 36.

Description of corner evidence found:

Found 4 inch diameter iron post with brass cap stamped.

Description of ~~monument and~~ accessories I established to perpetuate the ~~original~~ location of this corner:

Blazed and scribed the following new bearing trees.


Maple 10, bears N22E, 35.45 ft. or 53.712 lks.

Maple 13, bears S46E, 32.07 ft. or 48.590 lks.

Maple 6, bears S68W, 11.34 ft. or 17.182 lks.

Elm 7, bears N13W, 31.43 ft. or 47.484 lks.


43616360000



● = Corner monument restored

□ =

Resident witnesses.....

Dated at Rhineland Wisconsin, this 30 day of July 1969.Signature Jean F. Resvick Title Cadastral surveyor
(County Surveyor, Registered Land Surveyor, or other duly authorized official)Surveyors Registration No. S-802 DOCUMENT No. 98046Office of Register of Deeds County of Forest,
I hereby certify that the within instrument was filed in this office for record on the 22nd day of May 1970, and was filed in Book No. Page No. A-25 of County Records.Signature Eugene Stutzman Title Register of DeedsTownship 35 North, Range 16 East, Section 1, Index No. A-25, Page No. 


U. S. PUBLIC LAND SURVEY MONUMENT RECORD

INSTRUCTIONS: This record shall show the location of the corner and shall include all of the following nine elements (a through i).

- (a) Identify the corner by reference to the U.S. public land survey system.

● = Corner monument restored.

Section Corner common to Sections 1-6-31-36,
T.35-36N., R.16-17E., Forest-Marinette
Counties, Wisconsin.




- (b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

In 1857, Artemas Curtis set a wood post with the following BTs: Sugar, 18", S.12°W., 15 links; Sugar, 15", N.54°W., 26 links; Sugar, 15", N.40°E., 35 links; Yellow Birch, 18" S.70°E., 32 links. In 1934-35, J. J. Jenkins, Menominee County Surveyor, while surveying for Marinette County, set a 4" iron post for the corner. In 1936-37, F. Gould and B. Hammes, Deputy County Surveyors, said they found old post at corner and stumps checked for BTs. In 1969, J. Resvick (RLS) found a 4" iron post with a brass cap stamped for corner. He added the following BTs: Maple, 10", N.22°E., 35.45 feet; Maple, 13", S.46°E., 32.07 feet; Maple, 6", S.68°W., 11.34 feet; Elm, 7", N.13°W., 31.43 feet. In 1984, M. Stefan (RLS) found monument and accessories as per Resvick. Repainted BTs and added a steel sign post which bears north, 1.2 feet from corner. In 1988, A. Harrison found monument and accessories as per Stefan, found the Elm BT to be dead and replaced it with a Basswood, 8", N.41°W., 26.23 feet from monument.

- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.)
Describe witness monuments.

- (d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.

1. Marinette County Monument stamped to identify the corner.
2. Maple, 10", N.22°E., 35.45 feet
3. Maple, 13", S.46°E., 32.07 feet
4. Maple, 6", S.68°W., 11.34 feet
5. Dead Elm, 7", N.13°W., 31.43 feet
6. Basswood, 8", N.41°W., 26.23 feet
7. Steel Sign Post, North, 1.20 feet



- (e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

None.

- (f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

(2) a found perpetuated location.

- (g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

No.

- (i) I, Alan D. Harrison
(Type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature

Date

Certificate ready for filing:

Dale S. Staege
District Ranger

