

CERTIFIED LAND CORNER RESTORATION

State of Wisconsin }
County of Forest } ss.


History of original corner establishment:

I Thomas R. Arnott, do hereby
certify that on the 15th day
of December, 1975, I found
evidence of the M.C.
corner of sections 10 & 15 West of Pine Lake
Township 37, North, Range
12 E, Fourth Principal Meridian,
as described hereon; and that from this evidence
I established a new monument and accessories
as described hereon to perpetuate the original
location of this corner.

Original subdivision by William Daugherty Aug. 17 - Aug. 23 1859
Cedar 10 S35W 9 Lks.
Cedar 10 N10W 12 Lks.

Description of corner evidence found:
1 1/2" iron pipe with brass cap found

Resident witnesses:




Description of monument and accessories I established to perpetuate the original location of this corner:

Left iron pipe with brass cap

Ties:

SE corner of cottage	N39W	70.28 feet
NE corner of cottage porch	S54W	51.42 feet
Cedar post	East	4.90 feet
Cedar post	West	7.28 feet



○ = Corner monument restored.

Dated at Crandon, Wis., this 16th day of December, 1975.

Signature Thomas R. Arnott Title Land Surveyor Registration No. S-887
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Forest, I hereby certify that the within
instrument was filed in this office for record on the 16th day of December, 1975
at 11 o'clock A. M.

Eugene Stutzman Document Number 108400
(Register of Deeds)

By _____ Deputy