


# U.S. PUBLIC LAND SURVEY MONUMENT RECORD

Index No. R-5

State of Wisconsin }  
County of FOREST } ss.

I, John C. Schulke, do hereby  
certify that on the 2nd day  
of July, 1986, I found  
evidence of the Southwest  
corner of Section 20  
Township 37, North, Range  
12 East, Fourth Principal Meridian,  
as described hereon; and that from this evidence  
I established a new monument and accessories  
as described hereon to perpetuate the original  
location of this corner.

Resident witnesses:



○ = Corner monument restored.

History of original corner establishment:

Original Government Survey in 1859 by William Daugherty.

Original Bearing Trees: Birch 12" S72°E 7 lks.  
Birch 10" N82°W 5 lks.

Bearing GLO swamp calls  
South 297 feet  
North 1221 feet  
West 2112 feet

Description of corner evidence found:

Found charred fragments of wood post down about 1 1/2 feet in the ground.

Recovered stump holes from birch trees at the direction and distance described in the  
GLO notes.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 2 1/2" diameter aluminum pipe monument, 3 feet long, 2 feet in the ground,  
with an aluminum cap stamped; T37N, R12E, S19, S20, S29, S30, 1986, S-1665.  
Established the following new bearing trees which are blazed, scribed, painted  
and tagged.

Red Maple	5"	N46°W	24.58 feet
Red Maple	8"	N35°E	26.16 feet
Red Maple	6"	S54°E	16.64 feet
Red Maple	8"	S31°W	16.96 feet
Steel sign post		Northwest	1.0 foot

Dated at Ludington, Michigan, ~~Wis.~~, this fifth day of January, 1987

Signature John C. Schulke Title Land Surveyor Registration No. S-1665  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Forest, I hereby certify that the within  
instrument was filed in this office for record on the 24th day of February, 1987  
at 2:00 o'clock P. M.

Paul Aschenbrenner  
(Register of Deeds)

By \_\_\_\_\_ Deputy

REGISTER'S OFFICE

Forest County, Wis.

Received for record this 24th day  
of February A.D., 1987 at  
2:00 o'clock P. M. and recorded  
in Vol. 3-5 CORNER RESTORATIONS

Page 1  
Paul Aschenbrenner  
Register of Deeds

FORM NO. 985-A

H.C. Miller Company

Stock No. 26273

DOCUMENT NUMBER  
**132184**

43712190000

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

3/4" dia. iron pipe S31°E 38.72 feet

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

(1) an obliterated evidence location.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

5" Red Maple  
N46°W 24.58 feet

8" Red Maple  
N35°E 26.16 feet

Section Corner

S19	S20
S30	S29


6" Red Maple  
S54°E 16.64 feet

8" Red Maple  
S31°W 16.96 feet

3/4" dia. iron pipe  
S31°E 38.72 feet

(i) I, John C. Schulke  
(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Affix Land Surveyor Seal



John C. Schulke January 5th, 1987  
Signature Date

Certificate Ready for Filing: Dale B. Stage 2/24/87  
District Ranger Date