


U.S. PUBLIC LAND SURVEY MONUMENT RECORD

Index No. J-11

State of Wisconsin }
County of Forest ss.

I Gary L. Pisoni, do hereby
certify that on the 2nd day
of March, 1993, I found
evidence of the South Quarter
corner of Section 9
Township 37, North, Range
13 East, Fourth Principal Meridian,
as described hereon; and that from this evidence
I established a new monument and accessories
as described hereon to perpetuate the original
location of this corner.

Resident witnesses:



● = Corner monument restored.

History of original corner establishment:
Original Government Survey in 1865 by J.L. Nowlin. West corrected between Sections
9 and 16, at 40.35 chains, set Quarter Section Post to Sections 9 and 16, from which
the following bear;

| | | | |
|-------|-----|-------|---------|
| Sugar | 15" | N45°W | 20 lks. |
| Sugar | 8" | S10°E | 30 lks. |

Description of corner evidence found:
No original corner evidence was recovered. No other corner evidence was recovered.

I re-established the corner position at mid-point and on line between the Southeast
and Southwest Section Corners of Section 9.

Description of monument and accessories I established to perpetuate the original location of this corner.
At the corner position, set a 2½ inch diameter aluminum pipe monument, 3 feet long,
3 inches above the ground surface, with an aluminum cap stamped; T37N, R13E, 1/4,
S9, S16, 1993, S-1634. From which the following new blazed and scribed bearing trees bear;
(Measurements taken to a nail in side of tree)

| | | | |
|-----------------|-----|-------|------------|
| Sugar Maple | 13" | N12°W | 14.78 feet |
| Sugar Maple | 10" | N23°E | 33.82 feet |
| Sugar Maple | 12" | N64°E | 26.77 feet |
| Basswood | 12" | S37°W | 44.50 feet |
| Steel Sign Post | | West | 0.62 feet |

Dated at Iron River, MI, this 22nd day of April, 1993.

Signature Gary L. Pisoni Title Land Surveyor Registration No S-1634
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Forest, I hereby certify that the within
instrument was filed in this office for record on the 12th day of August, 1993.
at 1:25 o'clock P M.

By (Register of Deeds)
Deputy

FORM NO. 985-A
H.C. Miller Company
Stock No. 26273
DOCUMENT NUMBER
148152


4271309 0020

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?
Re-established through lost corner proportionate methods.



(i) I, Gary L. Pisoni
(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature

Date

Survey requested by:

District Ranger

Date

