DOCUMENT NUMBER

State	of Wisc	consin]
State County of	Fore	<u>st</u>	} 55.
certify that of Decemended Decement of the Corner of Last 14 East 14 East 14 East 15 East 15 East 16 E	on the ber Quar the Quar 4 & 37 thereon; and hereon to	11th , 19 rter Sect ourth Prince onument a	, do herebyday87, I found
Resident wit	nesses:	•	
N. Spies	s		·····
H. Wagon	er 		• • • • • • • • • • • • • • • • • • •
· ·	T37N_	R14E	<u>-</u>
	S_		1 - 1/4 -
O = Corner	monumer	t restored.	<u> </u>

O = Corner monument	t resto	red.
---------------------	---------	------

CERTIFIED LAND CORNER RESTORATION U.S. PUBLIC LAND SURVEY

Index No. C-9

History of original corner establishment:

Original corner established by J.L. Nowlin, Deputy Surveyor, in 1865 from which Fir 5" bears N54 E 20 1ks and Fir 6" S80 W 10 1ks.

Description of corner evidence found:

Recovered an old cedar stake rotted off at ground level. Found old stake point, also old beaver blazes on Hemlock 10" S80°E 12.22' and cedar 10" \$35°W 35.70'.

Corner perpetuated by Consolidated foresters and P.T. Hansen, Registered Land Surveyor since the late 1930's.

Description of monument and accessories I established to perpetuate the original location of this corner. Set a $2\frac{1}{4}$ " aluminum Forest County monument with $3\frac{1}{4}$ " alloy cap stamped: Monument projects 18" above ground. Marked NBT's T37N R14E Maple 4" S28°E 18.50' White Birch 10" N44°W 17.00' Scribed recovered old beaver blazes Hemlock 10" S80°E 12.22 Cedar 10" S35"W 35.70' 1987 S1682

Dated at	, Wis., this	day of	**-*	19
Signature Men Bauler	Title Control of the decrease	146	Registr	
Office of Register of Deeds, County of	Forest	aoaaaooaoo,,,,,,,,,,,,,,,,,,,,,,,,,,,,	, I hereby ce	rtify that the within
instrument was filed in this office for rec	ord on the 18th	day of	May	, 198.8
at 1:05 o'clock P. M.		·	•	
Faul Aschenbrenn	er,			
(Register of Deed	s) .			
Bv	Depu	t y		

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Perpetuated Location

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

GLEN
BARKER
S-1682
CRANDON
WI

OF SURVEYOR SCALE

OF SURVEY SCALE

OF SURV

(i) I, Glen Barker
(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signáture

May 18, 1988