		7

State of Wisconsin County of Forest I Glen Barker , do hereby certify that on the 12th day	
of October , 19 90, I found established Quarter Section corner of Sections 12 & 13	
Township 37, North, Range 14 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.	£.
Resident witnesses:	,
N. Spiess	
J. Spiess	
T37N R14E	

	T37N	RI4E	
	I	l 1	
	f I] [
·	-	!!	
	1		,*
	¦ S -	╎ ├- - 2- ┼	
	1	 	
	· 	 [
	〒		- -
	1	1/4	
	t	1/4	

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION U.S. PUBLIC LAND SURVEY RECORD

History of original corner establishment:

Original corner established by J.L. Nowlin, Gov't Deputy Surveyor.

Description of corner evidence found:

Re-established Quarter Section Corner on basis of survey stations and distances from original Chicago & Northwestern railroad plans.

Quarter Section Corner sets 2740.0' intermediate of the southwest and southeast Section Corner on a straight line between the two.

No evidence of previous corner.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1" Forest County aluminum pipe with 2-1/2" alloy cap stamped. Monument projects 6" above ground.

Marked N.B.T.s

Red Pine 7" N25E 79.04 '

Red Pine 8" N57E 73.97'

Red Maple 7" S80E 27.60' Twin Red Maple 6" S9E 42.66'

T37N R14E

S-1682

Corner sets 17.0' east of C.P.I. road.

Dated at Rhinelander	, Wis., this 14th	day of February	<u>91</u>
	· · · · · · · · · · · · · · · · · · ·	•	· ·


Signature Title Registered Land Surveyor Registration No. S-1682 (County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Found 19th day of June 19.2/ at / 20 o'clock P M.

(Register of Deeds)

Describe any material discrepancy between the location of the corner as restored reestablished and the location of that corner as previously restored or reestabled by distance and direction. Show the discrepancy on the plan view drawing under above. Show the distances between the corner as previously restored or reestables and (1) the corner as restored or reestablished, and (2) to at least 2 of the was monuments shown on the drawing in (d), above.

- (f) Was the corner restored through acceptance of (1) an obliterated evidence locates of (2) found perpetuated location?
 - Retracement of Railroad plan.
- (g&h) Was the corner reestablished through lost corner proportionate methods? If squared method, including the directions and distances to other public land survey communities evidence or used for proportioning in determining the corner location?



(i) I. Glen Barker

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Dow Saiker

6/18/91

Date

Affix CONSTRUCTION SCALE