CERTIFIED LAND CORNER RESTORATION

State of Wisconsin County of Forest	cc	
County of Forest	33.	
I found evidence of the sou Township 37 north	do hereby certify that on the 24th th quarter corner of Range 15 east Foundations I established a new monument and actions corner:	Section 23 rth Principal Meridian, as described
Surveyed in 1865 by J. L	ted between sections 23 and 26	ons:
Description of corner evidence	found:	
6x6 squared Cedar post Cedar stump bears N7W, 1 Tamarack stump bears S20 4 chains west leave swam		ar stump.
T37N R15E Blaz Ceda Ceda Ceda	ed and scribed the following new bear 7, N12E, 19.37 feet ar 6, S88E, 9.26 feet	
1973 S-802	el sign post set 1.0 foot northwest	of monument
	Resident witnesses	JEAN F. RESVICK
	Dated at Rhinelander	consin, Tail RHINELANDER day, of June 1
	1973	
Sec. 23	Signature Jean F. Reavick	Title and Service
	(County Surveyor, Registered Land Surveyors Surveyors Registration No. 2-802	DOCHMENT MIMEED
	Office of Register of Deeds	
= Corner monument restore	I hereby certify that the within instrume on the 13th day of November Corner Restorations No. R-19	
	Signature Line Section 23 Ind	Title Register of Deeds
Township 37 north Re	ange 15 east / Section 23 Uni	No. R-19 Page No.

43715230020