U. S. PUBLIC LAND SURVEY MONUMENT RECORD

INSTRUCTIONS:


This record shall show the location of the corner and shall include all of the following nine elements (a through 1).

(a) Identify the corner by reference to the U.S. public land survey system.

O = Corner monument restored.

O - Corner monument restored.

Section corner common to Sections 26, 25, 35, and 36, T37N, R15E, Forest County, WI.



(b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

Original survey by J.L. Nowlin in August 1865.


80.00 chains north, set section corner post.

20" birch - S48°E, 100 links 18" birch - N35°E, 9 links

In 1981 Milo Stefan, RLS, 1558 - set comer at intersection of fence lines. Set a 2" x 30" aluminum monument. No bearing trees or reference objects were established.

On 2/24/95, John Garske, RLS, found Milo Stefan's monument and made the following references below.

- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (witness monuments shall be made of concrete, natural stone, Iron orother equally durable material.)
 - (d) Show a plan view drawing depicting the relevent monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.
 - 1- 2" x 36" aluminum monument with cap stamped to identify corner.
 - 2- Fence post North, 15.46 feet.
 - 3- Steel sign post South, 2.35 feet.
 - 4- Fence post S11°W, 7.20 feet.
 - 5- Fence post S55°W, 1.88 feet.



(a) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d). above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

None

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location 7

2.

(g & h) Was the corner reestabilished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

No

1/4 COR.

(SOLAR BEARING)

35

N88-08-31"W 2475.78

26 25 35 36

FOUND 2"ALUM.
PIPE WITH STAMPED
ALUM. CAP

REGISTER'S OFFICE
Forest County, Wis.

page 37-15: V-21

Register of Deeds

JOHN R. GARSKE

S - 1685

IRONWOOD

MICHIGAN

John R. Garske, S-1685

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature

(1) 1.

CERTIFICATE READY FOR FILING:

4 65145

District Ranger

CERTIFIED LAND CORNER RESTORATION

State of Wisconsin	
State of Wisconsin County of Forest	[,] SS.
	do hereby certify that on the 9th day of September, 19.81,
I found evidence of the	Northwest corner of Section 36. Range 15 East Fourth Principal Meridian, as described
hereon: and that from this evi	dence I established a new monument and accessories as described hereon to per-
petuate the original location of	
Description of original monument and accessories and subsequent restorations:	
80.00 chains North, set	section corner post
20" Birch, S48E, 100	
18" Birch, N35E, 9 1	nks
•	
Description of corner evidence	found
Description of corner evidence	Touriu.
Fence corner, with fences	
	he by Bud Hansen, who was born and raised on the $NW_{4}^{\frac{1}{4}}$ $NW_{4}^{\frac{1}{4}}$ ily came to this area in 1904 and has been on said tract
since.	
-	
Description of monument and accessories I established to perpetuate the location of this corner:	
Placed a 2" x 30" aluminum monument 24" in the ground, supported by a mound of stone at base of fence corner.	
References:	
Steel Sign Post, Sout	th, 2.4 feet I as fields and pasture all around for 400 - 500
	MILO E.
	STEFAN
	DOCUMENT NO. RHINELANDER,
	124209 WIS.
	- CURVE 3
	Resident witnesses
	Dated at Laona Wisconsin, this 5th day of October
Section 36	19.81 Mile E Stefan Title Land Surveyor
	Signature Milo E. Stefan Title Land Surveyor. (County Surveyor, Registered Land Surveyor, or other duly authorized official)
	Surveyors Registration No1558
	Office of Register of Deeds County of Forest
	I hereby certify that the within instrument was filed in this office for record on the 13thday of September 1983, and was filed in Book
- Corner monument restore	on thePage Noof County Records.
	Signature Lugent Statesmy Title Register of Deeds
Township 37 North R.	ange 15 East Section 36 Index No. V-21 Page No.
- · · · · · · · · · · · · · · · · · · ·	
	43715210000