certify that of Decordence of the corner of	on the cember he Second	11th , 19.7. :tion .34 and 3	, do hereby day, I found orth, Range
as described I established	hereon; and la new mo hereon to	that from tonument and	al Meridian, his evidence l accessories the original
	nesses:	PHIL	IP T. SEN
	T37N	R15E	RVE
	S S	1 26 	
SC.		! [<u>{</u>	! !

O = Corner monument restored.

State of Wisconsin

Forest

CERTIFIED LAND CORNER RESTORATION

Index No.

History of original corner establishment: Original corner established by James McBride, Deputy Surveyor, in 1859.

No record of any subsequent surveys made.

This corner recovered by Ray Leigh in 1945. Recovered old wooden stake with an old iron pipe wired to it. Replaced old wood stake with 4" cedar post, squared and scribed.

Description of corner evidence found: Recovered 4" cedar post, squared and scribed S.26, 27, 34, and 35 in poor condition. Also recovered an old wooden squared cedar stake and a 1-1/2" iron pipe wired to it.

There was no trace of any OBT's visible in the area.

Description of monument and accessories I established to perpetuate the original location of this corner.

Replaced 4" cedar post with 2-1/2" Berntsen, A-1 Federal Monument, aluminum with magnet installed in cap and base. Pipe projects 18" above ground. Set 4" cedar post and old cedar post beside new pipe. Cap stamped - S498

W.C. S 15 lks. and another, W.C. West 25 lks. were set north and east of section corner.

Dated at	Argonne	, Wis., this	15th	da	y of	December	<u>, 19.75</u>
	County Surveyor, Reg						
	(County Surveyor, Reg	gistered Land Surveye	or, or other	duly auth	orized official	l)	
Office of Regi	ster of Deeds, County	of	Fore	st		, I hereby certify	that the within
nstrument w	as filed in this office for	r record on the	23rd	:	day of	December	, 1975.
	clock P. M.				•		
_	n State	m		I	OCUMENT	NUMBER 10	8443
	(Register of	Deeds	•				
3y	·····		Dep	outy			

Original Government Survey in 1865 by J. L. Nowlin, deputy surveyor.

In 1945, Ray Leigh recovered an old wooden stake with an old iron pipe wired to it. He replaced old wood stake with a 4" cedar post, squared and scribed. In 1975, Philip T. Hansen RLS recovered the 4" cedar post in poor condition, marking corner position. He replaced the cedar post with a 2½" Berntsen, A-1 Federal Monument with an aluminum cap. from which the following bear: (Corner sets in a tag alder marsh and set 2 witness corners)

13" dia. iron pipe with 2" brass cap stamped W.C. S 15 lks l¾" dia. iron pipe with 2" brass cap stamped W.C. West 25 lks

x Proximation of the above described value of 1/13/83, Milo Stefan RLS U.S.F.S. found the above described monument and set 2 steel sign posts: Steel sign post NW 2.3 feet Steel sign post NE 1.7 feet

Description of corner evidence found:

Found the monument and reference bearing objects as described above

1.7 feet Northeast Steel sign post 2.3 feet Steel sign post Northwest

ly" dia. iron pipe with brass cap 9.90 feet North 16.57 feet 13" dia. iron pipe with brass cap East

Description of monument and accessories I established to perpetuate the original location of this corner. Blazed and scribed the following new bearing tree: (Measurements taken to a nail in side of tree) N 71°W 118.11 feet White Spruce

= Corner monument restored.

State of Wisconsin

I Gary L. Pisoni do hereby

certify that on the <u>lst</u> day

of April , 19 94 , I found

cyidence of the Southwest Section

corner of <u>Section 26</u>

15 East., Fourth Principal Meridian,

as described hereon; and that from this evidence

as described hereon to perpetuate the original

established a new monument and accessories

County of Forest

location of this corner.

Resident witnesses:

Dated at	Iron River, MI	Wis., thisl3thday	of, 19	<u>95.</u> .
			Registration No.S-16	
Signature2	Wary 4. 1-20-	Title Land Surveyor	Registration No. S^{-1}	, 3 4
4.8		I I and Surveyor or other duly authoria		

Office of Register of Deeds, County of Apple 18. at / 30 o'clock M.

(Register of Deeds)


1: }	Describe any material discrepancy between the location of the corner as restored or
-	reestablished and the location of that corner as proviously restored or reestablished
•	by distance and direction. Show the discrepancy on the plan view drawing under (d),
	above. Show the distances between the corner as proviously restored or reestablished
	and (1) the corner as restored or reestablished, and (2) to at least 2 of the Witness
	monuments shown on the drawing in (d), above.

None

(r) was the corner restored through acceptance of (1) an oblicerated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.


(9kh) was the corner reestablished through lost corner proportionate mothods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



Section Corner S34 S35

(i)

Gary L. Pisoni ' Type or print name; certify that the corner location shown on this record was determined by me or under my direction and



District Ranger

Date

