History of original corner establishment:

Original corner established by James L. Nowlin, government deputy surveyor, in 1865, from which a aspen bears N38W 21 links and aspen 7" S21E 32 links.

Description of corner evidence found:

Re-established 1/4 corner by proportionate measurement. Total distance from section corner 3-4-33-34 T36&37N R15E to section corner 27-28-33-34 T37N R15E is 5280.71 .

Set 1/4 corner 2640.35' intermediate.

Description of monument and accessories I established to perpetuate the original location of this corner. Set a 2-1/4" aluminum Forest County monument with 3-1/4" alloy cap, stamped:

Monument projects 3" above ground. Marked BTs:

| Cedar | 12! | N18E | 62.04 |
|--------------|-----|-------|--------|
| Black Spruce | 7** | | 55.08' |
| Black Spruce | 10" | \$74E | 33.11' |
| White Birch | 10" | S51W | 26 051 |

T37N R15E $1/4 \quad S33 \mid S34$ 1986 S1682 Forest County

| Dated at | RhAnela | ınder | ., Wis., this | 12th | day o | of Janu | ıary | , 1987 |
|---------------|---------------|---------------------|---------------|--------------------|----------|--------------|-----------------------|------------------------|
| | How | Backer | | Registered | | | | on No. S1682 |
| J.6.1.a.c.a. | (County | Surveyor, Registere | ed Land Surve | yor, or other duly | authoriz | ed official) | 3 | |
| Office of Reg | gister of Dee | eds, County of | ord on the | rest 19th | da | av of Jan | hereby certif uary | y that the within 1987 |
| | 'clock P. | | | | | | | • |
| Dank | Asch | endenne | | | | | | |
| | | (Register of Deeds |) | | | | | |


County of Forest Glen Barker certify that on the 19th day of December 1986, I found established 1/4 corner of sections 33 & 34 Township 37...., North, Range 15 East Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner. Resident witnesses: N. Spiess H. Wagoner

O = Corner monument restored.

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

- (f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?
- (g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

proportionate method



(i) I, (type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature Laure

Date 8 1987

GLEN

BARKER

S-1682

CRANDON

WI