

## U.S. PUBLIC LAND SURVEY MONUMENT RECORD

Note: This form is intended and designed to fulfill all requirements of Wisconsin Administrative Code, Chapter A-E 7.08 U.S. Public Land Survey Monument Record (3)(a-l).

(a) CORNER LOCATION  
1/4 Cor. of Secs. 13 & 18Township 38 North  
Range 11 & 12 East of the 4th P.M.  
Town of Three Lakes  
County of OneidaWISCRS - Oneida County  
N: 214,779.56 USft  
E: 356,798.99 USft  
Datum: NAD 83(2011)  
GNSS Method: Static  
GNSS Control: WISCORS VRS

	SEC. 13		
	T38N R11E		

## (b) HISTORY OF ORIGINAL CORNER ESTABLISHMENT

Original Surveyor:

Original Accessories:

Date of Survey      Commenced:  
Completed:

(b)(f)(g)(h) Description of monument found at this corner and if it was accepted, state all evidence (material, testimonial, occupational, plats, records, other monuments) used as a basis for accepting. If not accepted or if nothing was found, state evidence used as basis for establishing location. If re-established through lost corner proportionate methods, indicate all monuments, distances and directions used to establish. Indicate type of monument and sign post found or set.

*This is a perpetuation of a previous USPLS Monument Record by James R. Grothman, RLS dated October 30, 1986 and filed in the office of the Oneida County Register of Deeds. A complete history of the corner can be found on the previous monument record. I accept the previous location as a true and faithful perpetuation or reestablishment of the original corner location and further perpetuate it as follows.*

*August 18, 2016: I found and accepted the record monument, a 2-1/2" diam. aluminum pipe with a 3-1/4" diam. aluminum cap projecting 14" above the ground surface. The existing accessories were found in substantial agreement with the record. and were not remeasured as the sole purpose of this work is to report the coordinates of the corner point.*

*The coordinate value shown has been verified by at least one of the following methods: 1) comparison to a previously GPS determined published value; 2) the value is the average of two or more GPS observations at a markedly different time; 3) one or more distances were measured back to the GPS observed corner from temporary GPS observed offset locations.*

(c)(d)(e) Plan view of corner with ties to at least 4 witness monuments. If in disagreement with previously established corner, show the distances between the two corners and also indicate the ties to the disputed.


FOREST COUNTY, WI  
CORTNEY BRITTEN CLEEREMAN  
REGISTER OF DEEDS  
RECEIVED FOR RECORDREGISTER OF DEEDS OFFICE  
ONEIDA COUNTY  
FILED

MAY 31 2018

DEC 28 2016

Time: 10:00 A M.  
Vol.: Corner Restoration  
Page Number: L-1AT        O'CLOCK        M  
KYLE J. FRANSON  
REGISTER OF DEEDS

(i) I, Michael J. Romportl, Professional Land Surveyor No. S-1624, hereby certify that the corner location on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.



Michael J. Romportl 12/23/2016  
Signature Date

3811132000 (INDEX NO. L-25)

4381132000

1-7