Index No. E-9

C-02-100	H.C.Miller Company From	
		į

U.S.	PUBLIC	LAND	SURVEY	MONUMENT	RECORD
<b>U</b> .	1 0000				

			U.S.	P
State	of Wisc	onsin	} ss.	
County of	Co1umb	<u>ia</u>	<b>.</b> J	
I JAMES certify that of	R. GROTH on the tober	MAN 10th 19	, do hereby day 86, I found	
Township	38	, N	North, Range oal Meridian,	
I established	d a new m	onument an	this evidence d accessories the original	
location of t		perpendic		
Resident wi	tnesses:		-	
.None				
***************************************				
******	******	* <del>*</del>		
	•			
	)	<u> </u>	1	
	1 1	! 	1	
  -	 <u> </u>	! !	l └	
	l [	l I -	<b>'</b>	
	l I	1	1	
	SEGTH	ON - 5	<del>'</del> <del>'</del> -	
	<b> </b> 	<b>l</b>	! . ! .	
	1 1		 	
	i — — — — !	. <del>-</del> 1	1	

O = Corner monument restored.

History of original corner establishment: Original survey by William E. Daugherty in 1859. Dependent resurvey by Wesson Cook in 1937. Set concrete monument 24 inches long 6 inches diameter, 20 inches in the ground reinforced with iron post 24 inches long, 1 inch diameter, with brass cap marked:

	R12E	From which	the follo	wing bear:						
<u>S5</u>	S4 S9	Cherry	3"	N18-3/4°E	35	1ks	${\tt marked}$	B.T. *		
		Maple	10''	S69°E				T38NR12E		
19	3/	Birch	4**	N77-3/4°W	57	1ks	marked	T38NR12E	S5	BT

Description of corner evidence found:

G.L.O. Monument found as described. No remaining evidence of bearing trees.

Description of monument and accessories I established to perpetuate the original location of this corner.

Corner in good condition. Blazed, scribed, painted, and posted the following new bearing trees:

Maple			10"		S3	35°E	I		12.20	feet
Maple			8"		N7	74 <b>°</b> E	İ	•	13.71	feet
Maple			611	•	$N_2$	28°W	•		27.20	feet
Maple			10"	•	S7	77°W	•		18.90	feet
Steel	post	1	foot	nor	th	of'	mor	un	ent	

Dated at HOZIAGE, Wis., this	30	day of OCTOBEE 19 86
Simple of the State of Field	KUS	Registration No. 152/
Signature County Surveyor, Registered Land Surveyor	or, or other dul	ly authorized official)
instrument was filed in this office for record on the	24th	day of <b>February</b> 1987
(County Surveyor, Registered Land Surveyor)  Office of Register of Deeds, County of Fore instrument was filed in this office for record on the at 2:00 o'clock P. M.		

Taul Mochenner (Register of Deeds)


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See G&H

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Corner was restored through acceptance of a found perpetuated location.

(9&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



District Ranger

Certificate ready for filing: