_					
U.S.	PUBLIC	LAND	SURVEY	MONUMENT	RECORD

ladas	NI.	F-23
Index	NO.	

	ate of V of Fore			} ss.
certify of evidence corner Townsh as desce I estab as desce location	that on the April e of the Senip 38 3 East ribed hereor hished a nearlibed hereor of this contact witnesses	Cochra 26 th South Quetion The specific control on the perion of the company of the control of t	ane 19.9 1arter l Principal t from the	2, I found orth, Range Meridian is evidence accessories
**************************************			••••••	
	l	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \]	

		<u> </u>	
) •	1
		,	I _
		ł	1
		I	1
	!	!	<u> </u>
		!	!
		Ī	
	!	Ţ	1
	SECTI	'hn 1	J
[М. т. — — .	<u> </u>
		!	!
		1	I
		1	1
		!	}
	<u> </u>	·	<u> </u>
		i	1
		1	
	!	1	1
	1	1	•
			l .

O = Corner monument restored.

History of original corner establishment:

Original Government Survey by H.& J. L. Nowlin in August 1865. West corrected between sections 1 and 12 at 40.20 chains, set Quarter Section post from which:

 Cedar
 12"
 S32°E
 12 1ks

 Spruce
 10"
 N12°W
 18 1ks

Description of corner evidence found:

No corner evidence was found.

Description of monument and accessories I established to perpetuate the original location of this corner.

At mid point between opposing Section Corners, set a $2\frac{1}{2}$ "X36" aluminum pipe monument $2\frac{1}{2}$ feet in the ground with an aluminum cap stamped: T38N, R13E, 1/4, S1, S2, 1992, S-1107. form which the following bear:

Maple 8" N12°E 20.38 feet
Maple 8" N64°E 17.07 feet
Steel sign post Northwest 1.00 feet

Dated at	Hiles	, Wis., this	4 th	day of <u>J</u> a	anuary	<u>19.95</u>
Signature. Will	County Surveyor, Register of Deeds, County of	ritle	Land Sur	yęyor	Registratio	n No. S-110
	(County Surveyor, Registe	red Land Surveyor	, or other duly	authorized officia	ıl)	
Office of Regist	ter of Deeds, County of the filed in this office for recock	Joles			, I hereby certify	that the within
instrument was	s filed in this office for re	cord on the	23.64	day of	august	19.26
at 2:30o'cle	ockM.					

(Register of Deeds)

Audience

Deput

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Re-established through lost corner proportionate methods

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

Maple 8"
N12°E 20.38 1

Maple 8"
N64°E 17.07

William B. Cochrane

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature B. Cochrane

Steel sign post

Northwest 1.00'

Date

WILLIAM B.

COCHRANE

S-1107

HILES,

WISCONSIN