State	e of V	Viscon	sin	ة م	1
County of,	Fores	st		} ss	5.
williant of	t on the Februar f the Sector 38 d hereoned a new ed hereoned a new ed hereoned a new ed hereoned a new ed hereoned hereoned hereoned hereoned a new ed hereoned a new ed hereoned here	ry Southe tion 1 ; and the monu	th 19 ast Se h Princi nat from ment ar	85 , 1 ction North, pal Me this ev	I found Range ridian, vidence
Resident w	ritnesses	;			
Day	vid Bro	ownell			•
To:	ay Til	lman			
	_				
					
					
	l 			 	
· -	 			 	
	 				· — —
					·
					·
			 +N- +		
		÷T •			
			 ·		
		→ - - - - - - - - - -			

History of original corner establishment: Original Government Survey in 1857 by Artemas Curtis. In 1964 Jean Resvick, a Land Surveyor with the U.S. Forest Service, found a 2" squared top cedar post in concurrence with original B.T. evidence. In place of post, set a 2" diameter galvanized iron pipe 5 feet long, with a brass cap stamped: T38N, R14E, R15E, S1, S6, S7, S12, 1964, S802. From which the following bear: N12°E 58.28 feet Aspen S35°E Aspen 33.15 feet N43°W 41.59 feet Aspen Description of corner evidence found: Found monument as described and in place from which the following bear: N12°E 58.28 feet Aspen 10" N43°W 41.59 feet Aspen S35°E 33.15 feet- cut down for Photo Project Aspen 4"x4" Cedar post SE 1.60 feet Description of monument and accessories I established to perpetuate the original location of this corner. Blazed and scribed a new bearing tree: S16°W 69.95 feet Spruce Dated at Hiles , Wis., this 8th day of March , 19.85

Cochrace
Signature William B. Cochrane Title Land Surveyor Registration NoS-1107

(County Surveyor, Registered Land Surveyor, or other duly authorized official) Office of Register of Deeds, County of Forest , I hereby certify that the within instrument was filed in this office for record on the 24th day of April , 19.85 at 1:00 o'clock P. M. (Register of Deeds)


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(9&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



R14E	R15E
S1	S6
S12	s7

WILLIAM B. COCHRANE S-1107 HILES, WISCONSIN

William B. Cochrane (type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

(i)