こののベンド	
Number	
Document	

	0		A		
U.S.	PUBLIC	LAND	SURVEY	MONUMENT	RECORD

Index	Nο	E-	23
HILLEX	INU.		

\
State of Wisconsin
State of Wisconsin County of Forest ss.
I William B. Cochrane do hereby
certify that on the 6th day
of October 19.83, I found evidence of the South Quarter
corner of Section 1
Township 38 North, Range
14 East Fourth Principal Meridian,
as described hereon; and that from this evidence
I established a new monument and accessories
as described hereon to perpetuate the original location of this corner.
rocation of this corpor.
Resident witnesses:
David Providali
David Brownell
Tony Tillman
t t
• · · · · · · · · · · · · · · · · · · ·

SECTION - -+
1 1

O = Corner monument restored.

History of original corner establishment:

Original Government Survey in 1865 by H.&J.L. Nowlin. West corrected between Sections 1 and 12, 40.20 chains, set Quarter Corner post to Sections 1 and 12, from which the following bear:

Hemlock	24"	S15°E	15 1ks.
Fir	12"	N 3°W	20 1ks.

Description of corner evidence found:

No original corner evidence was recovered.

The corner position was restored at proportionate distance and on line between the Southwest and Southeast Section Corners of Section 1.

Description of monument and accessories I established to perpetuate the original location of this corner. At the restored corner position, set a $2\frac{1}{2}$ diameter aluminum pipe monument, 3 feet long, 30 inches in the ground, with an aluminum cap stamped: T38N R14E, 1/4, S1, S12, 1983, S-1107. From which the following new blazed and scribed bearing trees bear;

₹.	Pine	6''	N63°E	4.02 feet
₹.	Pine	6"	N45°W	6.03 feet
Ste	el Sign	Post	SE	0.50 feet

Dated at Hiles	, Wis., this 3rd	day of	April	
Signature William B. Cock	land	Surveyor	Registration	*
(County Surveyor, Register	red Land Surveyor, or ot	her duly authorized offic	cial)	
Office of Register of Deeds, County of instrument was filed in this office for red	Forest ord on the 24th	day of	, I hereby certify April	that the withi
at 1:00 o'clock P. M. Paul Ascher				
(Register of Deed				
Ву	I	Deputy		


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.


See drawing below.

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through lost corner proportionate methods.

(96h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?





Steel Sign Post SE, 0.50 feet

(i) William B. Cochrane
(type or print name) certify that the corner location shows on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

William B. Cochrane Gril 3/985

Affix Land Surveyor Scal

WILLIAM B.

COCHRANE

S-1107

HILES,

WISCONSIN