J.S. PUBLIC LAND SURVEY MONUMENT RECORD

Index No.	J	—	25
-----------	---	----------	----

			0.5.
State	of Wisc	onsin]
County of	Forest		} ss.
,			/
		·	, do hereby
•			day
_		· ·	33, I found
			Section
		•	Vorth, Range
_			al Meridian,
		-	this evidence
I establishe	d a new mo	onument and	d accessories
		perpetuate	the original
location of t	his corner.		
Resident wi	tnoccoc:		
Resident wi	thesses.		•
Tony Till	man	************	
			<u>.</u>
	i .		
	1	! !	' ' 1
	1	' 	<u>'</u>
]	1	! 	· !
	} :	1	-
}	t I	1 [;
	' 	1	
	SFCTI	9N-12 -	<u>.</u>
j	' 	! [·
	I	•	†
1	<u> </u>	' i	<u> </u>
) 1		
1	, 1	1 1	
•		_	_

O = Corner monument restored.

History of original corner establishment:

Original Government Survey in 1857 by Artemas Curtis. North between Sections 13 and 18, 80.00 chains, set Section Corner post to Sections 7, 12, 13, and 18, from which the following bear:

Fir	8"	s37°W	33 1ks.
Fir	10"	N85°W	26 1ks.
Fir	8"	N56°E	40 $1 \mathrm{ks}$.
Fir	12"	S63°E	45 1ks.

Description of corner evidence found:

No original corner evidence was recovered.

The corner position was restored at proportionate distance and on line between the Northeast Section Corner of Section 12, and the Southeast Section Corner of Section 13.

Description of monument and accessories I established to perpetuate the original location of this corner.

At the restored corner position, set a $2\frac{1}{2}$ " diameter aluminum pipe monument, 3 feet long, 30 inches in the ground, with an aluminum cap stamped: T38N, R14E, R15E, S7, S12, S13, S18, 1983, S-1107. From which the following new blazed and scribed bearing trees bear:

Áspen	13"	N72°E	22.23 feet
Spruce	13"	S14°E	57 . 95 feet
Birch	811	N77°W	23.00 feet
Steel Sign P	ost	SW	0.50 feet

Dated at Hiles	, Wis., this 3rd	day ofApr	<u>:il</u>	19.85
Signature William B. Cochr. (County Surveyor, Regis	AMAL Title Land St stered Land Surveyor, or othe	rveyor r duly authorized official	Registratio	on No. <u>S-1107</u>
Office of Register of Deeds, County of instrument was filed in this office for rate 1:00 o'clock P	f Forest		, I hereby certify	that the within
4	enbrenner	·		

.....Deput


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through lost corner proportionate methods.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



WISCONSIN

(i) 1. William B. Cochrane
(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

William B. Cochrane april 3 1985