U.S. PUBLIC LAND SURVEY MONUMENT RECORD

Index	No	V	' —	2	5
moex	INO.	•			

State of Wisconsin County of Forest ss.
County of Forest
I William B. Cochrane , do hereby certify that on the 15th day of August , 19.83 , I found evidence of the Southeast Section corner of Section 25
Township
Resident witnesses:
David Brownell
Tony Tillman
•

 SEC-TH	ON-25	
 	! 	

O = Corner monument restored.

History of original corner establishment:

Original Government Survey in 1857 by Artemas Curtis. North between Sections 31 and 36, 80.00 chains, set Section Corner post to Sections 25, 30, 31, and 36, from which the following bear:

Sugar	14"	S20°W	21 1ks.
Sugar	12"	и60°W	30 lks.
Sugar	7**	N41°E	37 Iks.
Sugar	8''	S32°E	29 1ks.

Description of corner evidence found:

2" diameter iron pipe.

I accept the 2" diameter iron pipe as the best available evidence for restoring the corner position.

No original corner evidence was recovered.

Description of monument and accessories I established to perpetuate the original location of this corner.

In place of 2" diameter iron pipe, set a 2½" diameter aluminum pipe monument, 3 feet long, 30 inches in the ground, with an aluminum cap stamped: T38N, R14E, R15E, S25, S30, S31, S36, 1983, S-1107. From which the following blazed and scribed new bearing trees bear:

Maple	10"	N25°E	21.56 feet
Maple	6"	S74°E	38.52 feet
W. Ash	10"	S59°W	6.70 feet
Steel Sign	Post	North	1.00 feet

Dated at	H il es	, Wis., this	2nd	day of	April		19.85
Signature	County Surveyor, Register	ed Land Surveyo	Land S	Surveyor duly authorized o	official)	Registration No	S-1107
	ster of Deeds, County ofas filed in this office for recolockPM.	Forest ord on the	24th	day	of Apri	ereby certify that	the within 19.85
***************************************	Paul Asc (Register of Deeds		nev				
.R.,			Don				


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored from accepted evidence.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



Affix Land Surveyor Scal

"iscon.

WILLIAM B.

COCHRANE

S-1107

HILES,

WISCONSIN

William B. Cochrane

(i)

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land; Survey Monument Record is correct and complete to the best of my knowledge and belief.

William B. Cochrane april 2, 1985