		T_	25
Index	No.	1	

State of Wisconsin ss.				
County of Forest				
I William B. Cochrane , do hereby certify that on the 23rd day of August , 19.83 , I found evidence of the East Quarter corner of Section 25 Township 38 , North, Range 14 East , Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.				
Resident witnesses:				
Tony Tillman				
'. 'ı				
SECTION-25;				
· · · · · · · · · · · · · · · · · · ·				

O = Corner monument restored.

History of original corner establishment:

Original Government Survey in 1857 by Artemas Curtis. North between Sections 25 and 30, 40.00 chains, set Quarter Corner post to Sections 25 and 30, from which the following bear:

Sugar	14"	N40°W	$14 1 \mathrm{ks.}$
Ironwood	8"	S75°E	20 1ks.

Description of corner evidence found:

. 2" diameter iron pipe, 5 feet long, in a mound of stone.

I accept the iron pipe as the best available evidence for restoring the corner position.

No original corner evidence was recovered.

Description of monument and accessories I established to perpetuate the original location of this corner. In place of 2" diameter iron pipe, set a 2½" diameter aluminum pipe monument, 3 feet long, 30 inches in the ground, with an aluminum cap stamped: T38N, R14E, R15E, 1/4, S25, S30, 1983, S-1107. From which the following new blazed and scribed bearing trees bear:

Maple	8''	N82°E	7.70	feet
Maple	5"	South	23.88	feet
Steel Sign Post		NE	1.00	feet

Dated at <u>Hiles</u>	Wis., this	2/th	day	of	larch	, 19
ignature William B. Cochran	Title	Land	Surveyor			Registration No. S-1107
(County Surveyor, Registered	Land Survey	yor, or ot	her duly author	rized offic	ial)	
Office of Register of Deeds, County of	Fores	st	••••••		, I	hereby certify that the within
astrument was filed in this office for recor	d on the	<u>24th</u>		day of	Apri	<u>i 1</u> , 19 <u>85</u>
t 1:00 o'clock P. M.						
Paul Asche	mbren	nev				
(Register of Deeds)						
		_	_			

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored from accepted evidence.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

Steel Sign Post
NE, 1.00 feet

8" Maple
N82°E, 7.70 feet

Quarter Corner S25 S30

R14E R15E

Affix Lagran

Steel Sign Post
NE, 1.00 feet

8" Maple
N82°E, 7.70 feet

WILLIAM B.
COCHRANE
S-1107
HILES,
WISCONSIN

(i) William B. Cochrane
(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

South, 23.88 feet

William B. Cochrane M.

Date