211	DUDI IC	LAND	CHOVEY	MONUMENT	RECORD
U.S.	PUBLIC	LAND	SURVEI	MONOMEN	RECURD

		\/ ₋	. 7
Index	No	γ -	- <i>(</i>

State	of Wisc	onsin	} ss.		
County of	Forest	····	_		
I Gary L. Pisoni do hereby certify that on the 16th day of January 19.95. I found evidence of the North Quarter corner of Section 32 Township 38 North, Range 14 East Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.					
Resident wit	nesses:				
	· 		······································		
	**************************************		***********		
		· · · · · · · · · · · · · · · · · · ·			
	-	! !			
!		!			
1		1 I	: 1		
	SECTIO	N 32			
		1			
1]]	! !		
-		<u>-</u>			
] ,		[[
,		1 			

Corner monument restored.

History of original corner establishment:

Original Government Survey in 1865 by James L. Nowlin West corrected bet. Sections 29 and 32, at 39.50 chs., set Quarter Section Post, from which the following bear; Spruce, 7", N61°W, 45 lks., Tamarack, 6", S12°E, 10 lks.

In 1966, Jean Resvick, RLS, with the Forest Service, found a 4" X 4" squared cedar post with scribe marks in a ring of rock. Replaced cedar post with a 2" diameter galvanized iron pipe with a brass cap stamped to identify the corner. Blazed and scribed the following new bearing trees; Maple 11" N02 W, 25.88 feet

Y. Birch 6" S06 E, 31.79 feet

Description of corner evidence found:

Found monument and bearing trees as described above;

Sugar Maple	17"	N02°W	25.88 feet
Y. Birch(Dead)		S06°E	31.79 feet

Description of monument and accessories I established to perpetuate the original location of this corner.

Blazed and scribed new bearing trees; (Measurements taken to a nail in side of tree)

Sugar Maple	8"	N65 ⁰ Е	63.04 f	eet
Sugar Maple	8"	sl3°E	93 . 67 f	eet
Sugar Maple	9"	s39°w	42.94 £	eet
Steel Sign Post		588°E	1.10 f	eet

Dated at	Iron River, MI	x\visx. this	5th	day of	f March		19.95
	(County Surveyor, Register						
	(County Surveyor, Registe	ered Land Surveyo	y, or othe	r duly authorize	d official)	_	
Office of Re	egister of Deeds, County of.	So	est		<u>I</u> h	ereby certify	that the within
nstrument	egister of Deeds, County of, was filed in this office for resolved.	cord on the		dada	y o!	Lander	
••••••				*****			
	/n · / m						

gul Talleurez

Deputy

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as proviously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above. None


(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(96h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

No

17" Sugar Maple N02^OW, 25.88 feet



S13^OE, 93.67 feet

Gary L. Pisoni (1) (type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature

IRON RIVER,

MΙ

¥ 4 .

H. C. WILLER CO., HILWAUKEE 448643

CERTIFIED LAND CORNER RESTORATION

R9-5680-5 (7/15/64)

State of Wisconsin	
State of Wisconsin County of Forest ss.	
I Jean F. Reswick, do hereby certify that on the 16th day of August, 19.66. I found evidence of the North quarter corner of Section 32. Township 38 North Range 11 East. Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner:	- 1
Description of original monument and accessories and subsequent restorations: 39.50 chains west corrected between sections 29 and 32, set post for quarter corner. Spruce 7", N61°W, 45 1ks. Tamarack 6", S12°E, 10 1ks. Description of corner evidence found:	
Description of corner evidence found: Corner marked with 7 inch diameter cedar post top 3 ft. which was squared to 5x5.	
Post was 5 feet above ground in ring of rock. A lixly cedar post, 2½ ft. long, scribed ¼, was wired to west side of large post. This corner found marked and used by others has been in place for over 30 years.	
Description of monument and accessories I established to perpetuate the original location of this corner:	
Replaced cedar post with 2 inch inside diameter, galvanized iron pipe, 5 feet long, flanged at bottom, filled with concrete with brass tablet marked:	
Т38N R14E	
From which the following blazed and scribed new bearing trees bear: Maple 11", N2°W, 25.88 ft., 39.21 lks. Yellow birch 6", S6°30'E, 31.79 ft., 48.17 lks. Resident witnesses	
Dated at Rhinelander Wisconsin, this 6 4 day of 19.67. Signature Jean F. Resvick Title Cadastral Surveyor (County Surveyor, Registered Land Surveyor, or other duly authorized official) Surveyors Registration No. S-802 DOC. NO. S-268 Office of Office Register of Deeds County of Forest I hereby certify that the within instrument was filed in this office for record on the 2nd day of March 19.67, and was filed in Book	., 1
Signature Signature States of Deeds Township 38 North Range 11 East Section 32 Index No. V-7 Page No. V-7 Pa	- {

43814290020