1278
Number
Document

CERTIFIED LAND CORNE	R RESTORATION
----------------------	---------------

History of original corner establishment:

No evidence of any previous corner.

Description of corner evidence found:

Corner established by subdivision of SW 1/4 section 29. Location of SW 1/16 is 1353.79' of SC 1/16 and 1313.95' of WC 1/16.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1" iron pipe with 2" diameter alloy cap stamped: Monument projects 18" above ground. Marked NBTs:


> Cedar 12" N15E 2.31' Yellow Birch 10" East 3.09'

		Sle	82
		T3	38N
SW	1/16	S_	<u>2</u> 9
		R]	L4E
	(	PT-	-1985

Dated at	Rhimelander	Wis this.	18th	day of	April	
	(County Surveyor, Register			<del>-</del>		ation No. <u>S1682</u>
						•
	gister of Deeds, County of was filed in this office for recolockA	Forest ord on the	3rd	day o	I hereby cer May	tify that the within 19.85
	Paul Aschent (Register of Deed		<u>, , , , , , , , , , , , , , , , , , , </u>	-		•:

## State of Wisconsin County of Forest I Glen Barker , do hereby certify that on the 28th day 19.85 I ACCOUNT corner of Section 29 \_\_\_14\_East\_\_\_\_\_, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner. Resident witnesses:

N.	Spiess	
R.	undt	
	~	-



O = Corner monument restored.