CERTIFIED LAND CORNER RESTORATION	
State of Wisconsin	
State of Wisconsin County of Forest	iS.
I found evidence of the North Township 39 North	day of April 19.64, heast Section corner of Section 10. Range 12 East Fourth Principal Meridian, as described nce I established a new monument and accessories as described hereon to perise corner:
Description of original monument	and accessories and subsequent restorations:
sections 2, 3, 10 and 11 we with brass cap mkd. T39N R A maple, 10 in. diam. A maple, 12 in. diam. A maple, 10 in. diam.	
Description of corner evidence fo	
A maple, 20 ins. of A white pine stump A maple, fallen, b	cribed above from which iam., bears S 18° 30' W, 180 lks. dist. , bears N 58° W, 182 lks. dist. scribing readable. ears N 77°E, 161 lks. dist. scribing readable. iam., S 18°E, 252 lks. dist.
	essories I established to perpetuate the original location of this corner:
_	REGISTER'S OFFICE Forest County, Wis. Received for record this 21 day of Max A. D., 19 65 at 9:30 o'clock A. M. and recorded in Value I of Corner Best page E-17 Anna PETERSON Karl A. Ungar Ay Register of Deeds
	Resident witnesses Dated at Rhinelander Wisconsin, this 27/A day of April
	19.65. Signature Jean F. Resvick Title Cadastral Surveyor
Section 10	Signature Jean F. Resvick Title Cadastral Surveyor (County Surveyor, Registered Land Surveyor, or other duly authorized official) Surveyors Registration No. S=802
	Office ofCounty of
	I hereby certify that the within instrument was filed in this office for record on theday of19, and was filed in Book
Corner monument restored	No
	SignatureTitle
manalia 20 Manth D	
Township	e 12 East , Section 10 , Index No. E-17 , Page No

R9-5680-5 (7/15/64)

H. C. WILLER CO., MILWAUKEZ 448643