


# U.S. PUBLIC LAND SURVEY MONUMENT RECORD

Index No. J-19

State of Wisconsin }  
County of Forest ss.

I, Gary L. Pisoni, do hereby certify that on the 6th day of September, 1990, I found evidence of the South Quarter corner of Section 11, Township 39 North, Range 13 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:



● = Corner monument restored.

## History of original corner establishment:

Original Government Survey in 1865 by William E. Daugherty and Alex McDill.

Dependent Resurvey in 1978 by Gary L. Kratz and Michael J. Avery. N89°45'W between Sections 11 and 14, at 37.90 chains, proportionate distance, set an aluminum post, 30" long, 2½" in diameter, 10" in the ground, in a mound of stone, and a cap marked; T39N, R13E, 1/4, S11, S14, 1978. From which the following bear;

Maple	8"	S28°E	32 links
Maple	7"	N52°W	17 links

## Description of corner evidence found:

Found monument as described, from which the following bear;

Maple	8"	S28°E	21.12 feet (20.55 feet)
Maple	7"	N57°W	11.22 feet (11.00 feet)

Distances in parenthesis are my measurements taken to a nail in side of tree.

## Description of monument and accessories I established to perpetuate the original location of this corner.

Blazed and scribed the following new bearing trees; (Measurements are taken to a nail in side of tree)

Maple	8"	S87°E	25.04 feet
Maple	7"	S54°W	11.60 feet

Dated at Iron River, MI, this 20th day of August, 1990.

Signature Gary L. Pisoni Title Land Surveyor Registration No. S-1634  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Forest, I hereby certify that the within instrument was filed in this office for record on the 10th day of March, 1993 at 10:45 o'clock A.M.

Paul Aschmussen  
(Register of Deeds)

By Deputy

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.


See drawing below.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?


7" Maple  
N57°W, 11.00 feet



7" Maple (NBT)  
S54°W, 11.60 feet

8" Maple  
S28°E, 20.55 feet

8" Maple (NBT)  
S87°E, 25.04 feet



(i) I, Gary L. Pisoni  
(Type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature

Gary L. Pisoni

Date

11/21/91

Survey requested by;

Pam Gordon  
District Ranger

Date

12/15/92