CE	RTIFIED LAND CORNER RESTORATION
State of Wisconsin County of Forest	•
I found evidence of the North Township 39 North	, do hereby certify that on the 11 day of May
Description of original monument	and accessories and subsequent restorations:
Surveyed in 1865 by William 80.00 chains North between Spruce 7, N50W, 9 1ks. Birch 7, S60E, 13 1ks.	\mathbf{i}
Description of corner evidence for	nd:
5x5 scribed cedar post Rotted stump N50W, 9 1ks. Tamarack 5, Dead and fallen Chained west 40 chains foun Distance North and South to Post has been in place 40 t	d quarter corner
Replaced post with a 2 inch	JIN SCONS
Spruce 16, N87E, 16.99 ft. Tamarack 7, S21E, 9.29 ft. Spruce 8, S49W, 46.55 ft. Spruce 9, N79W, 20.36 ft.	WILLIAM B. COCHRANE S-1107 HILES, WISCONSIN
	Resident witnesses
Sec. 8	Dated at Laona Wisconsin, this 21 day of July 19.77 William B. Cochrane Title Survey Technician (County Surveyor, Registered Land Surveyor, or other duly authorized official) Surveyors Registration No. S-1107. DOCUMENT NUMBER 113307
	Office of Register of Deeds County of Forest I hereby certify that the within instrument was filed in this office for record on the 13th day of February 19.78, and was filed in Book No. Page No. of County Records.
Township 39 North Range	Signature Liquid Section 8 Index No. E-9 Page No.

43914050000