U.S. PUBLIC LAND SURVEY MONUMENT RECORD

Matai		
Note:	This form is intended and designed to fulfill all requirements of Wisconsin Administrative (Code. Chapter A-E 5.02, U.S.
	Public Land Survey Monument Record (3) (a) (b) (c) (d) (e) (f) (g) (h) (i). An additional sheet	may be added if necessary to
	conform with said requirements.	
(a) Co	orner location: Township 40 North	
	Danes 12	

Hiles Town/City/Village Forest . County

Section

(b) (f) (g) (h) Description of monument found at this corner and if it was accepted, state all evidence (material, testimonial, occupational, plats, records, other monuments) used as a basis for accepting. If not accepted or if nothing was found, state evidence used as basis for establishing location. If reestablished through lost corner proportionate methods, indicate all monuments, distances and directions used to establish.


Found 2" diameter brass capped iron pipe stamped identifying the corner. The monument was re-established from the 1941 General Land Office Dependent Resurvey.

BT's recovered from the 1941 Resurvey: 16" S. Maple $S 32^{\circ}3/4^{\circ} \cdot E$ 52.14 16" S. Maple . :N 64 3/4⁰ E 50.49

REGISTER'S OFFICE Forest County, Wis. Received for record this. 7_day of Hecensula A.D., 19.88 at 10:10 o'clock H.M. and recorded in Vol. CORNER RESTOR ATIONS

Register of Deeds


(c) (d) (e) Plan view of corner with ties to at least 4 witness monuments. If in disagreement with previously established corner, show the distances between the two corners and also indicate the ties to the disputed corner.



Note: measurements are to nail set in rootcrown of tree.

Stephen J. Favorite RLS#S1616 (type or print name) certify that the corner location on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

<u>8. 1988</u> <u> Abril</u> Date Signature Survey requested by; 11/88 District Ranger Date



46-12