· CE	RITHED LAND CORNER RESTORATION
State of Wisconsin	
State of Wisconsin County of Forest	
I found evidence of the North quantity Township 40 North	, do hereby certify that on the <u>lst</u> day of <u>June</u> , 19 73, arter corner of <u>Section 19</u> , Range <u>12 East</u> , Fourth Principal Meridian, as described ce I established a new Management accessories as described hereon to personner:
Description of original monument	and accessories and subsequent restorations:
Surveyed in 1859 by William Dependent Resurvey in 1941 beat At proportionate distance so with brass cap marked 1/4, 8 Poplar 6, bears S62W, 32 1ks Yellow Birch 22, bears N26W,	by Guy R. Veal st an iron post, 3 feet long, 2 inches in diameter, 318, S19, 1941
Description of corner evidence fou	nd:
Monument as described above Yellow Birch stump bears N26	5W, 86 1ks.
Description of MOTHNERWAND accompliance and scribed the follow Balsam 7, N28W, 10.32 feet Spruce 6, S77E, 13.23 feet Set galvanized sign post 1 in	
	Resident witnesses Dated at Rhinelander Wisconsin this Zone Early Earl
Township 40 North , Range 12 East , Section 19 , Index No. N-3 , Page No.	

4401218 BBZB