## 44013160020

| 985-A  |   |
|--------|---|
| ,<br>0 | į |
| FORM   |   |
| _      |   |

## DOCUMENT NUMBER

| US   | PUBLIC  | IAND | SURVEY | MONUMENT  | RECORD |
|------|---------|------|--------|-----------|--------|
| U.J. | LODFIC. | LANU | SURVEI | MICHORIEM | RECURD |

|       |     | N-11  |
|-------|-----|-------|
| Index | No. | 14_TT |

| State  | of Wisconsin  | າ<br>} ss.                              |
|--|---|---|
| County of  | Forest  |   |
| certify that of Sep evidence of corner of Township 13. East as described I established | liam B. Cochra on the 12th tember the North Qua Section 2 40 Fourth F hereon; and that d a new monume hereon to perpe | nday 1day 1                             |
| Resident wi  | tnesses:  | •                                       |
| 40-1   |   |   |
| ***************  | ••••• <u>•</u> •••••  | *************************************** |
|  |   |   |
|  |   |   |
|  |   |   |
|  |   | l<br>                                   |
| <br>   | <br><del> </del>  | <del> </del>                            |
|  |   | '  <br>                                 |
|  | SECTION 2   | 21                                      |
|  | i   | <del>-</del>                            |
|  | <b>1</b>  | j<br>I                                  |
|  | i -   | <del> </del>                            |
|  | ]<br>   |   |
| ,  | 1<br>   | <u>'</u>                                |

O = Corner monument restored.

History of original corner establishment:

Original Government Survey in 1865 by William E. Daugherty. West corrected between Sections 16 and 21, at 40.42 chains, set Quarter Section Post, from which the following bear;

Hemlock 10" S72°E 33 1ks. Hemlock 12" N06°W 6 1ks.

Description of corner evidence found:

No corner evidence was recovered.

I re-established the corner position at proportionate distance and on line between the Northwest and Northeast Section Corners of Section 21.

Description of monument and accessories I established to perpetuate the original location of this corner. At the corner position, set a  $2\frac{1}{2}$  inch diameter aluminum pipe monument, 3 feet long,  $2\frac{1}{2}$  feet in the ground, with an aluminum cap stamped; T40N R13E, 1/4, S16, S21, 1991, S-1107. From which the following new blazed and scribed bearing trees bear;

 J. Pine
 10"
 S05°W.
 6.17 feet

 J. Pine
 9"
 N67°W
 7.30 feet

 Set- Steel Sign Post
 NE
 0.50 feet

| Dated at       | Hiles                                      | , Wis., this                                   | 19th     | day of            | February     | <b>19</b>       |
|----------------|--|--|----------|-------------------|--------------|-----------------|
| Signature W.   | lliam B. C.                                | chrane Title                                   | Land     | Surveyor          | Registration | No. S-1107      |
|                | (County Survey)                            | or, Registered Land Surveyor.                  | or otner | auiv authorizea o | (mciai)      |                 |
| Office of Regi | ster of Deeds, Co<br>as filed in this offi | unty of <i>Hotelat</i><br>ce for record on the | ر<br>رک  | day o             | of Current   | that the within |
| at 10:15 o'c   | Jack Ase                                   | M.<br>hertrenner                               |          |                   |              |                 |
|                |  | ter of Deeds)                                  |          |                   |              |                 |

| (e) | Describe any material discrepancy between the location of the corner as restored or   |
|-----|---|
|     | reestablished and the location of that corner as previously restored or reestablished |
| ••  | by distance and direction. Show the discrepancy on the plan view drawing under (d),   |
|     | above. Show the distances between the corner as previously restored or reestablished  |
|     | and (1) the corner as restored or recstablished, and (2) to at least 2 of the witness |
|     | monuments shown on the drawing in (d), above.   |

See drawing below.

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

(g&h) was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

Re-established through lost corner proportionate methods.

Steel Sign Post

MSCON.

WILLIAM B.

COCHRANE

S-1107

HILES,

WISCONSIN

S17 S16 GLO 40.42 chs. 1/4 GLO 40.42 chs. S16 S15 S20 S21 2770.66' 2770.65' S21 S22 S88°02'-00"E

9" J. Pine(New BT)
N67°W, 7.30 feet

Quarter Corner \$\frac{\frac{516}{521}}{21}

10" J. Pine(New BT) S05°W, 6.17 feet

(i) I, William B. Cochrane
(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

William B. Cochrane March 25, 1992

Survey requested by; Survey requested by; District Ranger Date