0
8
Q
4
-
28
Ġ
<u>~</u>
\bigcirc
7
7
1

FORM NO. 985-A	HC Miller Company [74]

262/3	NUMBE	700
ė Ž	INI	S
Stock	DOCUMENT	14

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

		17
Index: No.	. ♦ 🔻	エン

State of Wisconsin	} ss	History of original corner	ēstablishment:	*. *		•	,
County of Forest	J. 33.		•	365 by William E. Da	augherty. North	h between	
Milliam B. Cochrane	Single Company	Sections 27 and 28	_	ains, set Quarter Se	 1		
certify that on the 22nd	, do hereby	following bear;	1 · · ·)			
of August 19 91		Hemlock Birch	20" 18"	S51°W	24 1ks.	P.	. ,
cvidence of the West Quarte	. -	birch	19.	NO9°E	25 1ks.		-
corner of <u>Section 27</u>	•						•
Township 40 No	·	·~				•	
13 East Fourth Principal	•	Description of some suice	·. 4 (_	
as described hereon; and that from the I established a new monument and		Description of corner evid	·			•	
as described hereon to perpetuate the		Found a ½" diamete	r iron rod in	a mound of stone.	•	r	÷
location of this corner.	-, "	Location post with	tag on road t	to West.		€° S.	, -
Resident witnesses:		Nororigināl corner	evidence was	recovered,	•		`
**-*		I accept the iron	rod as the bes	st available evidend	e for restori	ng the corner	position.
***************************************							-
		T)			,1 1 1		-
		Description of monument	and accessories i	established to perpetuat	e the original local	tion of this corner	Γ•
٠.٠		$2\frac{1}{2}$ feet in the gro	und, with an a	inch diameter alumin luminum cap stamped lowing new blazed a	l; T40N R13E, 1	1/4, S27, S28,	
		Maple		S16°E	10 24 E-54	-	
		Maple Maple	8 ^{11.}	N59°W	19.24 feet 12.04 feet		
		Steel Sign Pos	st	East	0.50 feet		
-	·						
1 1	•1						
i t		_	;				
SECTION 27 !].	Dated at Hiles	s· ı	Wis. this 19th	day of Febr	uary	10 9
		1.00	- 0 D	11 13., 11113	uay Ut	,	, 19
\$: I		Signature William &	3. Cochrane	/ Title Land Sur		Registration	No. S-1107
		-	•	Land Surveyor, or other duly	·	_	
		Office of Register of Deed		SOLOT		hereby certify t	hat the with
		instrument was filed in the at 10:15 o'clock	<i>A</i>	on the 3/54	day of	ugust	, 19
				7			
1 1 1		Taul	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	enner	-	•	•
			(Register of Deeds)				
O = Corner monument restored.	- •	By		Deputy			


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

(f) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored from accepted evidence.

(gkh) was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

8" Maple (New BT) N59°W, 12.04 feet



11" Maple (New BT) S16°E, 19.24 feet

William B. Cochrane (type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature

Survey requested by;

District Ranger

May 4, 1992

MISCONS,

WILLIAM B.

COCHRANE

S-1107

HILES,

WISCONSIN