## CERTIFIED LAND CORNER RESTORATION

State of Wisconsin	•
State of Wisconsin  State	
I found evidence of the <u>East</u> Township <u>40 North</u>	day of September 1976,  Ouarter corner of Section 12  Range 14 East Fourth Principal Meridian, as described ace I established a new monument and accessories as described hereon to personner:
Description of original monument	and accessories and subsequent restorations:
From remains of origina 30 ins. in the ground we Yellow Birch, 18 ins.	temas Curtis L945 by Hugh B. Crawford al bearing tree, set iron post 3 ft. long, 2 ins. diam. with brass cap marked 1/4, S12, S7, 1945. diam, bears N82E, 39 1/2 lks. distance. bears N47W, 61 lks distance.
Description of corner evidence for	ınd:
Monument as described a Yellow Birch snag, scriben Hemlock stump, fallen	above. ibed, bears N82E, 39 1/2 lks. tree scribed, N47W, 61 lks.
•	
Description of monument and acc	essories I established to perpetuate the location of this corner:
Blazed and scribed the Balsam 5, N43E, 48 1/2 Red Pine 6, S89W, 100 Set sign post North sign	$3/4~{ m lks.}$
44	\$14122999  BY RESVICK RHINELANDER,
	Resident witnesses
Sec. 12	Dated at Rhinelander Wisconsin, this decign of September 19.76.  Signature Jean F. Resvick Title Land Surveyor (County Surveyor, Registered Land Surveyor, or other duly authorized official)  Surveyors Registration No. S-802 BOCUMENT NUMBER- 11092
	Office of Register of Deeds County of FOREST  I hereby certify that the within instrument was filed in this office for record
- Corner monument restored	on the 31st day of January 19.77, and was filed in Book
	No. Page No. of County Records.  Signature Lugene States of Deeds
Township40 North Rang	e 14 East Section 12 Index No. G-25, Page No.