Index No. L-13

	J.S.	PUBLIC	LAND	SURVEY	MONUMENT	RECORD
--	------	--------	------	--------	----------	--------

U.S. 1	PUBLIC LAND SURVEY	MONUMENT	RECORD		Index No. L-13
State of Wisconsin } ss.	History of original corner estab	lishment:	•	•	
County of Forest	Original Government Sur		Wm. E. Daught	erty North hetwo	0.0 <b>n</b>
I Gary L. Pisoni do hereby	Section 15 and 16, 40.0	00 chains, set	Quarter post to	Sections 15 and	16, from which
certify that on the 9th day	the following bear: Fir	6"	s.10°w.		•
of September 19.86, I found	Fir	8''	N.66°E.	18 links 16 links	Ł
cyidence of the <u>East quarter</u> corner of <u>Section 16</u>				TO TIME	
Township40, North, Range				<b>*</b>	
14 East Fourth Principal Meridian,		· ·			
as described hereon; and that from this evidence I established a new monument and accessories	Description of corner evidence	found:			
as described hereon to perpetuate the original	No corner evidence was	recovered.			
location of this corner.	The corner position is	re-established	at proportions	sto diatores and a	1
Resident witnesses:	between the Northeast a	nd Southeast So	ection corners	of Section 16.	on Tine
Mark Selmo	•			-	Ţ
	·				\ \
					į,
-					
**************************************	Description of monument and a			<del>_</del>	
	At the corner position, 33" in the ground, with	set a 2½ inch an aluminum ca	diameter alumi an stamped: TAC	num pipe monument	, 3 feet long, 5
	S-1634. From which the	following new	blazed and scr	ibed bearing tree	s bear (all
	measurements taken to a	nail in side o	of tree);		
	Balsam Black Cher	rv 8"	S.89 E. S.10 W.	22.88 feet	
	Balsam	9"	N.16°W.	63.19 feet 24.03 feet	
	Steel sign	post	s.73°w.	1.19 feet	
		•			·
SECTION 16	Dated at Iron River,	MI , Wisx, this	s. 5th	day of May	19.87
	$\mathcal{N}_{1}$		T J		
	Signature Xay o - 1-2 (County Surveyo	r, Registered Land Sur	Land Suveyor, or other duly au	thorized official)	gistration No.S-1634
	Office of Register of Deeds, Cou			•	y certify that the within
		ce for record on the	18th	day of March	1988
	at 12:50 clock P.	v1.			•
	Jan 1/8che	norennes	; 	•	
	(Regist	er of Deeds)			

O = Corner monument restored.


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through lost corner proportionate methods.

(gkh) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



Affix Land Surveyor Scal

GARY LEE

PISONI

S-1634

IRON RIVER,

MI

SURVENIMENTO

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

District Ranger

Signature Say S. Fr.

of a legan

3-8-88

Survey requested by:

(i)

Date