	C
	CT/ATTIA
	E
	TATE TATE
	E
	Č

State	of Wiscons	in )	\$S.				
County of	Forest	}	\$5.				
County of Forest  I Gary L. Pisoni do hereby certify that on the 7th day of November 19.89, I found evidence of the Southeast Section corner of Section 22  Township 40 North, Range 14 East Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.							
Resident wit	nesses:						
<u> </u>	i	i					
j ;	] 1	1 1					
		1					
<del>-</del>	i - ·	<del> -</del> -					
1	1	1					
1 ,	SECTION	_22					
, 1	- I	l 					
	1	1					
	·	<del> </del> -					
. !	· ·	. !					
,	[	- <del> </del>					
<u></u>	monument res		•				

History of original corner establishment: Dependent resurvey in 1950 by Hugh B. Crawford, N 01°40'W between Sections 26 and 27, 40.87 chains, corner determined from a 4" squared cedar post, no remaining evidence of the original bearing trees; at the corner position, set an iron post 30" long,  $2\frac{1}{2}$ " diameter, 24" in the ground with brass cap marked: T40N, R14E, S-22, S-23, S-27, S-26, 1950 from which the following bear: 1944 corner references: Cedar 12" N 63°E 77 links, Cedar 12" S 32½°E 158 links
Yellow Birch 22" S 63°W 76 links,
1950 corner reference: Cedar 12" N 81 3/4°W 141 links Description of corner evidence found: Found monument as described above. Corner references found: 50.82 feet Cedar 104.28 feet Cedar 50.16 feet Yellow Birch  $N 81 3/4^{\circ}W$ 93.06 feet Cedar Description of monument and accessories I established to perpetuate the original location of this corner. New reference object: s 47°E 1.05 feet Steel sign post

Dated at	Iron River, MI	Wis. this	9th	day of	December	. 19. 89
Signature	Lang L. Pesmi	Title	Land	Surveyor	Registra	tion No. S-1634
	(County Surveyor, Register	ed Land Survey	or, or other	r duly authorized of	ficial)	
Office of Renstrument	(County Surveyor, Register egister of Deeds, County of was filed in this office for reco'clock	ord on the	ST - 20	day o	I hereby cert	ify that the within
Ву	(Register of Deeds	s)	De	puty	•	

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(i)

Signature

Survey requested by;

(r) was the corner restored through acceptance or (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(9kh) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

17" Cedar N 65°E, 50.82 feet 16" Cedar N 81 3/4°W, 93.06 feet Section Corner ♥Steel sign post S 47°E, 1.05 feet 28" Yellow Birch S 63°W, 50.16 feet **PISONI** S-1634 IRON RIVER. 20" Cedar ΜI s 32  $1/4^{\circ}E$ , 104.28 feet Gary L. Pisoni (type or print name) cectify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the pest of my knowledge and belief.

Date

District Ranger

Date