State	of Wisc	onsin	} ss.
County of	Forest	·····	Sas.
certify that of evidence of corner of Township 14 East as described I establishe	on the July the Nort Sect 40 hereon; and hereon to	6th 19 hwest Section 32 urth Principonument and	North, Range day day Meridian, this evidence daccessories the original
Resident wi	tnesses:		
***************************************		•	
			······
			*:
•			
•	<u> </u>	- 	
	<u>.</u> I	- i !	
	!	 	
	ī — — — — 		!
	SECTION	 	I ·
- -	. '2EC III	עוע <u>ט</u> ב .	1 -
	! .: 		
 	 		<u> </u>
	 		i I
	 	<u> </u>	
C	monument	monto-od	

LAND SURVEY MONUMENT RECORD Index No. V-5 History of original corner establishment: Original Government Survey in 1865 by William E. Daugherty. North between Sections 31 and 32, 80.00 chains, set Section Corner post to Sections 29, 30, 31 and 32, from which the following bear; S.48°E. N.11°W. 31 links Sugar 12" 42 links Hemlock Description of corner evidence found: Found a bent iron pipe along West edge of a logging road. I accept the iron pipe as the best available evidence for restoring the corner position. Description of monument and accessories I established to perpetuate the original location of this corner. In place of iron pipe, set a $2\frac{1}{2}$ inch diameter aluminum pipe monument, 3 feet long, flush w/ground surface, with an aluminum cap stamped; T40N, R14E, S29, S30, S31, S32, 1989, S-1634. From which the following new blazed and scribed bearing trees bear (all measurements taken to a nail in side of tree):

Sugar	Maple	14"	S.85°W	64.86	feet
Sugar 1	•	10"	S.85°E.	45.23	fee
Sugar 1	Maple	6 ''	S.33°E.	59.27	fee
Sugar 1	Maple	10"	N.22°W.	38.10	fee
Steel S	Sign Post		N.47 ^O W.	1.00	fee

Dated at	Iron R	iver, MI	, Wis ., this	2nd	day of	November	
				•	_		
Signature Land Surveyor Registration No.S-1634 (County Surveyor, Registered Land Surveyor, or other duly authorized official) Office of Register of Deeds, County of Local Land Surveyor, or other duly authorized official) I hereby certify that the within instrument was filed in this office for record on the day of Lecture Level 19.20. at 15.0'clock M.							
at 10:45 o'clock 1 M.							
	ا م	(Register of Dee	ds)				:

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.


(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored from accepted evidence.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

10" Sugar Maple(NBT)

N.22°W., 38.10 feet



6" Sugar Maple(NBT) . S.33°E., 59.27 feet [

GARY LEE
PISON
S-1634
IRON RIVER,
MI

Gary L. Pisoni

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature Samp di Ja

Jan 12 1996

Date

Survey requested by;

(i)

9-18-2

Date

District Ranger

JISTIICE Nai