CERTIFIED LAND CORNER RESTORATION


Description of corner evidence found:

State of Wisconsin

Concrete monument as described above. Spruce 15, N10^O30'E, 76 lks. Spruce 16, N 2W, 70 1ks.

Description of monument and accessories I established to perpetuate the original location of this corner:

No new accessories added.



			ŀ
	Sec.	31	
= Corner monument restored			

	Resident witnesses
	Dated at Rhinelander Wisconsin, this 15 day of August
27	19.72. Signature Jean F. Resvick Title Land Surveyor
Sec. 31	County Surveyor, Registered Land Surveyor, or other duly authorized official)
	Surveyors Registration No. S-802
	Office of Register of Deeds County of Forest
	I hereby certify that the within instrument was filed in this office for record
= Corner monument restored	on the 18th day of October 19.72, and was filed in Book No. I Page No. Z-3 of County Records.
	Signature Liquid States of Deeds
Township 41 North Range	13 East , Section 31 , Index No. Z-3 , Page No.

44113310020

DOCUMEN'I

NUMBER