	0
	~
	0
	T
	1
•	I
	7
	4

FORM NO. 985-A H.C. Miller Corneany [F2] Location recognition [F2]

Stock No. 26273

DOCUMENT NUMBER 132429

_					
115	PURIC	IAND	SURVEY	MONUMENT	RECORI
U. J.	I UDLIC	LAIN	2017461	MOUDITE	

Index No.	A-15
-----------	------

State of Wisconsin County of Forest ss.	History of original corner establishment:
I William B. Cochrane do hereby certify that on the 23rd day of July 19.86, I found evidence of the North Closing Quarter corner of Section 3 Township 40, North Range 14 East Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.	NONE Description of corner evidence found: NONE
Resident witnesses:	The corner position is established at proportionate distance between the Northeast and Northwest Section Corners of Section 3, and on line between the Standard Quarter
David Brownell	Section Corner of Section 34 and the Standard Section Corner common to Sections 34 and 35, T41N R14E.
Tony Tillman	
	Description of monument and accessories I established to perpetuate the original location of this corner. At the corner position, set a 2½ inch diameter aluminum pipe monument, 5 feet long, 3½ feet in the ground, with an aluminum cap stamped; T41N R14E, S34, S3, N1/4, CC, 1986, S-1107. From which the following new blazed and scribed bearing trees bear; Tamarack 6" S29°W 11.91 feet Tamarack 10" N39°W 27.08 feet Steel Sign Post NW 1.00 feet
SECTION 3	Dated at Hiles , Wis., this 28th day of October , 19
	Signature William B. Cochrace Title Land Surveyor Registration No. S-1107 (County Surveyor, Registered Land Surveyor, or other duly authorized official) Office of Register of Deeds, County of Forest Ilth day of March 19.87 at 3:30 o'clock P. M. (Register of Deeds)
O = Corner monument restored.	ByDeputy

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

- (f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?
- (g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

Established through lost corner proportionate methods.

