Index No. V-19

		consin	} ss.
County of	Forest		}
ofAug evidence of corner of Township 14 East as describe	t on the	Jst	, do hereby day 91, I found ter North, Range pal Meridian, this evidence
			nd accessories e the original
	this corner.	•	
Resident w	itnesses:		
			•
			
	•	l	
	\ \ \ \ \	l !	1
	\ \ \ \ \ \ \ \ \	l 1 1	1 1
		l 1 1 1	
	SECT	 - - QN_26_	
	SECT	i 	
		ION_26_	
	SECT	ION_26_	
	SECT	ION_26_	
		ION_26_	

=	Corner	monument	restored.
---	--------	----------	-----------

History of original corner establishment:
Original Government Survey in 1865 by William E. Daugherty. West corrected between Sections 26 and 35, at 40.12 chs., set Quarter Section Post to Sections 26 and 35, from which the following bear;

Tamarack 6" S30°E 14 lks.
Spruce 5" N15°W 11 lks.

Description of corner evidence found:
No original corner evidence was recovered.

I restored the corner position at proportionate distance and on line between the Southwest and Southeast Section Corners of Section 26.

Description of monument and accessories I established to perpetuate the original location of this corner. At the corner position, set a $2\frac{1}{2}$ inch diameter aluminum pipe monument, 3 feet long, 3 inches above the ground, with an aluminum cap stamped; T41N R14E, 1/4, S26, S35, 1991, S-1634. From which the following new blazed and scribed bearing trees bear; (measurements taken to a nail in side of tree)

		^ '	
Balsam	811	N44°W	17.65 feet
Balsam	9"	N11 ^O E	19.12 feet
B. Cherry	711	N79 ^O E	14.97 feet
W. Spruce	13''	\$84 ⁰ E	61.24 feet
Steel Sign Post		West	0.64 feet

Dated at	Iron River, MI	,¼₩¼¾, this	16th	day of	February	<u> </u>
Signature	Dany L. Puson, (County Surveyor, Registe	Titlered Land Surveyor	Land Surv	eyor v authorized o	Registra	tion NoS-1634
Office of Reinstrument	gister of Deeds, County of was filed in this office for re-	cord on the	10 ×	day o	I hereby cert	ify that the within
at 10:45	Clock A. M. Register of Dece	Krane		-		
	(Register of Deed		_	•		


(a) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a round perpetuated location?

Restored through lost corner proportionate methods.

(9kh) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location? Reestablished through lost corner proportionate methods.



S.27 S.26	G.L.O. 40.12 chs. <i>2630.55</i>	1/4	G.L.O. 40.12 chs. 2630.55	S.26	S.25	Sunning State	<u>k</u>
S.34 S.35	N86° 30'/3"W		5261.10	s.35	S.36	GARY LEE PISONI S-1634 IRON RIVER, MI	MINIMAN PRINTERINGE

G.L.O. 40.12 chs.

Affix Land Surveyor Scal

Lype or print name; certify that the corner location shown (i) on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

G.L.O. 40.12 chs.

Survey Requested by; District Ranger Date