Stock No. 26273

(C) (C) (T)	
CTT CATTLE)
TIME TIME	

	U.S.	PUBLIC	LAND	SURVE	Y MC	DNUME	NT	RECO	RD
State of Wisconsin	} ss.	History of original corner establishment:							
unty of <u>Forest</u>		_	•	nment Su			bу	Artemas	Cur

_		Z-3	
Index	NIA		
HILLEX	IXU.		

State of Wisconsin					
County of Forest ss.					
I. William B. Cochrane, do hereby certify that on the 30th day of July 19.86, I found evidence of the Standard Quarter Section corner of Section 31 Township 41, North, Range 14 East Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.					
'Resident witnesses:					
David Brownell					
Tony Tillman					
SECTION 31					

Original Government Survey in 1858 by Artemas Curtis. Dependent Resurvey in 1945
by Hugh B. Crawford. East on the South side of Section 31, 42.60 chains, found original
bearing tree evidence. From evidence, set an iron post, 3 feet long, 2 inches in dia.,
28 inches in the ground, with a brass cap mkd; SC, 1/4, S31, 1945. From which the
following bear:

 Poplar
 4"
 N73°30'E
 31 1ks.(20.46 feet)

 Poplar
 4"
 N21°00'W
 6 1ks.(3.96 feet)

Description of corner evidence found:

Found monument as described and in place, from which a Poplar (Stump) bears N21°W, 3.96 feet.

No evidence of other Poplar bearing tree:

Description of monument and accessories I established to perpetuate the original location of this corner.

No Bearing Trees Available.

, Șteel Sign Post

South

1.00 feet

4411431002

Dated at	Hiles		, Wis., this	25th	day of	September	
	ulliam 6	Cochran	Title	Land Sur	veyor	Reg	istration NoS-1107
	(County Su	rveyor, Registere	d Land Survey	yor, or other di	ily authorized (official)	
Office of Reg	ister of Deeds as filed in this	, County of s office for reco	Forest	11th	day	of March	certify that the within 1987
	Daul	Aschen	Grenne				
	(F	Register of Deeds)					•
_				_			


(e)	Describe any material discrepancy between the loc	
	reestablished and the location of that corner as	previously restored or reestablished
	by distance and direction. Show the discrepancy	
	above. Show the distances between the corner as	previously restored or reestablished
	and (1) the corner as restored or reestablished,	
	monuments shown on the drawing in (d), above,	

See drawing below.

(r) was the commer restored through acceptance or (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



Steel Sign Post South, 1.00 feet

Affix Land Surveyor Scal

WILLIAM B.

COCHRANE

S-1107

HILES,

WISCONSIN

(i) i, William B. Cochrane
(type or print name) certify that the conner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

William B. Cachrane October 14, 1986

Certificate ready for filing:

District Ranger

Date