13246	
NUMBER	
DOCUMENT	

U.S.	PUBLIC	LAND	SURVEY	MONUMENT	RECORD
U.U.	. 05510	- 6-110		1410140141E141	

	-				mdex No	
State of Wisconsin } ss.	History of original corner establishment:					
County of Forest William B. Cochrane	Original Government Survey in 1858 by Artemas Curtis. Dependent Resurvey in 1945 by Hugh B. Crawford. East on the South side of Section 32, 39.65 chains, at proportionate distance, set an iron post, 3 feet long, 2 inches in dia., 27 inches in the ground, with a brass cap mkd; SC, 1/4, S32, 1945. From which the following bear;					
evidence of the Standard Quarter Section corner of Section 32 Township 41 North, Range 14 East Fourth Principal Meridian,	Cedar Balsam	6" 8"	S79°30'E S 9°15'E	162 1ks.(106.92 feet) 56 1ks.(36.96 feet)		
as described hereon; and that from this evidence	Description of corner ev	idence found	d:			
I established a new monument and accessories as described hereon to perpetuate the original	Found monument as described and in place, from which the following bear;					
ocation of this corner. Resident witnesses:	Balsam Cedar(Stump)	14"	S 9°15'E S79°30'E	36.96 feet 106.92 feet		
David Brownell					•	
Tony Tillman						
**************************************	Description of monumen	it and acces	sories I established	to perpetuate the original location	on of this corner.	
	Blazed and scribed	a new bea	aring tree;			
· · · · · · · · · · · · · · · · · · ·	R. Pine Steel Sign Pos	10" st	N22°E South	31.35 feet 1.00 feet		
				•		
SECTION 32	Dated at Hiles	<u>;</u>	, Wis., this	25th day of Septer	nber 19 86	
	Signature William (County	Surveyor, Reg	gistered Land Surveyor	Land Surveyor r, or other duly authorized official)	Registration No. S-1107	
	Office of Register of Dee	ds. County	of For	rect	nereby certify that the within arch 19 87	
Corner monument restored.	By	(Register of I	Deeds)	Deputy		

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.


f.

(i)

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(9&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



14" Balsam S 9°15'E, 36.96 feet

type or print name; certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

SUR SUR SON

HILES,

WISCONSIN

Signature Ochsone October 17, 170

Certificate ready for filing:

District Ranger

Date