
## CERTIFIED LAND CORNER RESTORATION

State of Wisconsin	SS.	•	-		-
County of <u>Forest</u>	_ <b>SS.</b>		•		•
I Jean F. Resyick		<del>-</del>			•
I found evidence of theNo					
Township 41North					
hereon; and that from this e		a new monument	and accessories a	as described here	eon to per-
petuate the original location of	orner:				
Description of original monur	ment and accessories	and subsequent res	storations:		
Original survey 1860 by	Alfred Millard.	•			•
Dependent resurvey by G	uy R. Veal in 19	41.			
From remains of origina	l bearing trees.	Set a concret	e monument, 2	ft. long, 6	ins. diam.
18 inchs in the ground,	<del>-</del>	•	Rs12 and 13E.	. with brass	cap
marked, T42N, R13E, S36		•			
Sugar Maple, 10 ins. di				•	
Sugar Maple, 6 ins. dia		·	•	•	
Sugar Maple, 12 ins. di	. · <b>V</b> .	-			
Hemlock, 16 ins. diam.		S.	•	•	
Description of corner evidence					
Concrete monument marke	_				
Sugar 13, bears N5E, 61 Sugar stump, S61E, 91 1	_				•
Sugar 16, S57W, 46 1ks.			•		
Hemlock 15, N40W, 13 lk		v 12 inche who	n scribed ·		
Hantock IJ, Haon, IJ IK	s. Hemrock approx	A. IZ INCHS WITE	i sciibed.		
	•				•
		-			

Description of museum accessories I established to perpetuate the original location of this corner:

Set steel sign post 1 ft. SW of monument.



RESVICK