

LANGLADE COUNTY  
U.S. PUBLIC LAND CORNER RESTORATION

The Quarter corner common to Sections 2 & 3, T. 30 N., R. 12 E., Langlade County, WI.

Corner was: (check all that apply)

- ☐ Restored through acceptance of an obliterated evidence location.
- ☒ Restored through acceptance of a found perpetuated location.
- ☐ Determined to be lost and re-established through proportionate methods.
- ☐ Show bearings and distances to PLSS corners used for proportioning, and show original distances).
- ☐ Restored/recovered/re-established in a location that differs from a previously established position.
- ☐ (Show difference in plan view below).
- ☐ Check here if additional information is shown on the reverse side of this form.


Corner history:

The original corner was established in 1854 by James Withrow. Original bearing trees: tamarack, 9", S46E, 50 links and a tamarack, 10", N20-1/2W, 48 links. Surveyor Wegner used a four way fence corner on a 1937 survey. In 1993, surveyor Edwin Abendroth set an aluminum monument at the fence corner and marked 4 bearing trees. On May 5, 2026, I found the aluminum monument frost heaved and leaning. I reset in firmly at fence corner post hole, top of the monument is 12" above ground level. This location works very well with two remaining Abendroth bearing trees as shown below. Even though there is no tie back to the original government survey, I believe the fence found in 1937 may have been set using some kind of evidence (bearing trees or local testimony) of the original corner location.

Physical description of the monument set:

I reset the existing aluminum monument.

Describe the accessories used to perpetuate the corner. Include a plan view drawing and accessories found/set. Describe measuring point on bearing trees. Show any topographic features that would aid in future recovery of the corner.



Tree ties are measured to an aluminum nail in a low blaze on the side of the tree. Trees have "Survey Marker" sign facing the corner.

White vinyl sign post set 1' north of monument.

Tie bearings are magnetic with hand compass  
*Info in italics is Ed Abendroth information*

Langlade County Coordinate system values  
NAD 83 (2011) datum

O = corner perpetuated

The East Quarter  
corner of Section 3,  
T. 30 N., R. 12 E.,  
Langlade County, WI

I, David E. Trusty, Wisconsin Professional Land Surveyor S-1390, do hereby certify that the corner location and perpetuation shown on this record was made by me and that this U.S. Public Land Survey Monument/Record as required by AE-7.08 of the Wisconsin Administrative Code is in correct to the best of my knowledge and belief.

C 17 30-12

43012032000


U. S. PUBLIC LAND SURVEY MONUMENT RECORD

INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following nine elements (a through i).

- (a) Identify the corner by reference to the U.S. public land survey system.  
O = Corner monument restored.


West  $\frac{1}{4}$  corner, Sec. 2, T30N, R12E  
Set Berntsen standard county monument



- (b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

Fence corner which was used on Wegner survey of N  $\frac{1}{2}$  SW  $\frac{1}{4}$  Sec. 2-30-12 Dated 9-22-37

- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.)  
Describe witness monuments.



- (d) Show a plan view drawing depicting the relevant monuments and the reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.

Magnetic bearings with blaze and nail in tree.

43012032000

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

Demension between West  $\frac{1}{4}$  corner and center of section 2698.96 record 2699.44 measure.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location.?

(2)

(g & h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location.

No

(i) I, Edwin R. Abendroth  
(type or print name)

certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Edwin R. Abendroth 6-17-93  
Signature Date

