

4331101 2000 2026

U.S. PUBLIC LAND SURVEY MONUMENT RECORD - LANGLADE COUNTY

Note: This form is intended and designed to fulfill all requirements of Wisconsin Administrative Code, Chapter A-E 7.08 U.S. Public Land Survey Monument Record (3)(a)(b)(c)(d)(e)(f)(g)(h)(i). An additional sheet may be added to it if necessary to conform with said requirements.

(a) Corner Location:

Wisconsin Corner ID: 43311012000

Type of Monument: Survey Nail

Location: East Quarter Corner

Section 1, Township 33 North, Range 11 East,

Town of Upham, Langlade County, Wisconsin

Langlade County Coordinates NAD83(2011):


Northing: 424576.13

Easting: 646763.12

RTK GPS direct observation

Calibrated to HMP DQ4952 (Pearson GPS)

3 position average on 5/8/2026



(b)(f)(g)(h) Description of monument found at this corner and if it was accepted, state all evidence (material, testimonial, occupational, plats, records, other monuments) used as a basis for accepting. If not accepted or if nothing was found, state evidence used as basis for establishing location. If reestablishment through lost corner proportionate methods, indicate all monuments, distances and directions used to establish. Indicate type of monument found or set and sign post.


- ORIGINAL - Aug. 1857 - Millard, Alfred - Set quarter section post. Cedar 10 S45W 4 lks, Hemlock 11 N46E 8 lks.
- 1936 - Map #50005 - D.A. Hintz shows corner 40.01 chains from SE section 1, and 38.65 chains from the NE section 1.
- Oct. 1983 - Edwin Abendroth - Tie Sheet - Found an existing 3 inch iron pipe monument with cap, set in 1936 by the U.S. Forest Service, 33 feet north of section corner.
- Jan 1993 - Map #40101 - Daniel Higginbotham found 4" iron pipe with brass cap 2555.31' from NE section 1.
- 5/8/2026 - Chad Besaw - Set Survey Nail per found 4" brass capped iron pipe witness monument - slightly tipped - stood straight, and 2 remaining ties from Abendroth's 1983 tie sheet. Made new references.

(i) I, Chad A. Besaw, Wisconsin Professional Land Surveyor #S3029, hereby certify that the corner location on this record was determined by me and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.


Chad A. Besaw

6/11/2026

Date



(c)(d)(e) Plan view of corner with ties to at least 4 witness monuments. If in disagreement with previously established corner, show the distances between the two corners and also indicate the ties to the disputed corner.



C 25 33-11


U. S. PUBLIC LAND SURVEY MONUMENT RECORD

INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following nine elements (a through i).

- (a) Identify the corner by reference to the U.S. public land survey system.

O = Corner monument restored.



West $\frac{1}{4}$ Corner, Section 6, T33N, R12E, Town of Ainsworth, Langlade County, Wisconsin.


T33N R12E

- (b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

Found an existing 3 inch iron pipe monument with cap, set in 1936 by the U.S. Forest Service, 33 feet north of section corner.

- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.)
Describe witness monuments.

- (d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.



C-25

33-11

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

Corner restored as previously restored.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

(2)

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

No

(i) I, Edwin R. Abendroth
(type or print name) certify that the corner location shown
on this record was determined by me or under my direction and
control and that this U.S. Public Land Survey Monument Record is
correct and complete to the best of my knowledge and belief.

Edwin R. Abendroth
Signature

Oct 17, 1983
Date

