

This survey was taken  
in the years 1932-1934.

SURVEY

W<sub>2</sub> of 34 - 12

Charles W. Borth

## ABBREVIATIONS

acre	ac.
angle	/
approximate	approx.
Balsam	bal.
bears	brs.
between	bet.
birch	bir.
cords	ods.
corner	cor.
hardwood	Hwd.
intersect	int.
jack pine	j pine
original	Orig. or Ogl.
reproduction	rep.
section	sec.
spruce	spr.
standing	stg.
tamarac	tam.
variation	var.

Red numbers on line in index or on separate pages indicate page numbers from the original North Field notes.

# INDEX

T54N R12E

44	45	46	47	48	49
6	5				
90	91	92	93	94	95
7	8	9	10	11	12
86	87	88	89	90	91
15	16	17	18	19	20
80	81	82	83	84	85
17	18	19	20	21	22
76	77	78	79	80	81
30	29	28	27	26	25
70	71	72	73	74	75
31	32	33	34	35	36
67	68	69	70	71	72

RED NO. INDICATES PAGE

# AINSWORTH FOREST UNIT BOUNDARY

1935-1936

32

N random bet secs 31 & 36 to  $\frac{1}{4}$  Var  $4^{\circ}$  E.

Cor to twp's 33 & 34 N. Ranges 11 & 12 E  
1 Orig. B.T. 7 ft. Tam stump 10N  $18^{\circ}$ E 39 lks.  
Other B.T.'s gone. Old rotted stake, pump head  
on E side of stake, set and scribed new cedar  
stake.

26.375 Ft.

$\frac{1}{4}$  bet 36 & 31 \* This  $\frac{1}{4}$  falls in the N wheel  
track of C.T.H. Q. B.T.'s appear to have been  
destroyed in road side cleanup.  
\* Int E & W  $\frac{1}{4}$  line 37.8 ft. E of  $\frac{1}{4}$  bet 31 & 36.  
Error 1.4 $\frac{1}{4}$  pr. 100'.

33

S on random bet 31 & 36 to  $\frac{1}{4}$  Var  $5^{\circ}$  E.

Cor to secs 25-30-31-&36 has scribed cedar stake  
and Orig. B.T.'s Tam 10S  $22^{\circ}$ W 17 lks. Stump B.T. shows  
Tam 10 N  $62^{\circ}$  W 38 lks. Stub scribes plain  
Tam 10 S  $67^{\circ}$  E 31 lks. Gone but roots.  
Tam 10 N  $18^{\circ}$  E 17 lks. Rotten stump  
Later B.T. Tam 9 S  $62\frac{1}{2}^{\circ}$ E 47 lks. scribes about  
gone.

26.375 Ft.

Later B.T. Tam 10 N  $81^{\circ}$ W 74 lks. stub scribes  
plain.  
Int E & W  $\frac{1}{4}$  line 79.8 ft. W of  $\frac{1}{4}$  bet 36 & 31.  
Error 3'  $\frac{1}{4}$  pr. 100'.

N corrected bet 31 & 36, Var  $3^{\circ}$   $10'$  E.

3.00 Ft.  
7.75 "  
7.75 "  
11.85 "  
22.00 "  
26.375 "

Set station stakes W to true line. Cor in swamp.  
Int Hunting River at Westerly bend.  
Leave Hunting River measured on ice.  
High land 4" to 6" Aspen and white bir.  
Int  $1/8$  stake which is 133.7 ft. too far S.  
Enter spruce swamp. Rep good 6' to 30'.  
 $\frac{1}{4}$  sec post in C.T.H. Q.

N from  $\frac{1}{4}$  bet 31 & 36, Var  $3^{\circ}$   $20'$  E.

28.00 Ft.  
34.00 "  
47.25 "  
52.75 "

Enter 6' to 8" cedar & tam swamp.  
Leave swamp for 3" aspen & w. birch ridges  
Enter spruce, cedar, tam, swamp recently slashed  
Rep scattering.  
Cor to secs 25-30-31-36.

34  
5.00 Ft.  
14.00 "  
19.00 "  
26.053 "

N random bet secs 25 & 30 Var 4° E.  
from cor described on page 33.  
Enter open sage brush non-productive swamp.  
Enter good stand green tam 6" to 8".  
Leave swamp for 10' aspen point some scattering  
pine 6" to 8".  
Int  $\frac{1}{4}$  line 54.2 ft. W of  $\frac{1}{4}$  bet 25 & 30. Old  
rotten scribed stake down. Ogl B.T.'s gone.  
Unrecorded B.T.'S Y pine stump 16 S 56°E 37.3'  
rotted W pine stump 16 S 15°W 11.5'  
burnt W pine stump 12 N 30°W 10.5'  
No visible scribes on either W. Pine B.T.  
New B.T. Norway 10 N 75° E 62.3'  
Set and scribed new cedar stake.

52.306 Ft.

N on random bet 25 & 30 from  $\frac{1}{4}$  Var 2° E.  
Int E & W sec line 9' E of cor to secs 24-25-30-19.  
Old scribed pine stake about rotten. Set and  
scribed new tam stake.  
B.T.'s Ogl W pine 18 S 58° E 220 is rampike shows  
old face no scribes.  
Ogl Y pine 15 N 78 E. rotten stump  
Recorded B.T. W. pine about rotten S31 $\frac{1}{2}$ °E 31 lks.  
Recorded B.T. W pine stump N40 $\frac{1}{2}$ °E 86 lks.  
This cor is recorded in County Records as cor to  
secs 19 & 30 and Ogl Govt Field notes call for  
this cor as a Witness Cor at 78.50 N.

13.026 Ft.  
26.053 "

N corrected bet 25 & 30 to  $\frac{1}{4}$  Var 3° E.  
1/8 rotten set new tam stake.  
 $\frac{1}{4}$  bet 25 & 30

30.95 Ft.

N corrected bet 25 & 30 from  $\frac{1}{4}$  Var 1° 48' E.

47.00 "

Wolf River and enter hay marsh. Good white and  
Noway pine. Rep between  $\frac{1}{4}$  and Wolf River. Fair  
recreation spot accesable from C.T.H. Q on high land  
Leave marsh for E end of aspen point, recently  
burnt, rep 12' to 20' poor.

52.306 "

W.C. to sec's 19-30-24 & 25 cor in slough.  
New B.T. Bir 6 S 45° E 11 ft.

S bet 19 & 24 from  $\frac{1}{4}$  Var 2° 30' E.

27.016 Ft.

36  
This  $\frac{1}{4}$  bet 19 & 24 has no ogl or recorded B.T.'s  
has 1" iron pipe even with ground 1' N of 8"  
cedar post flattened on two sides. Made + on  
SW cor of flint rock 4' high which bears N 21°E  
111.2' from cor.  
Fell 9.5' E of W.C. for cor to secs 19-30-24 & 25.

37

26.40 Ft.

S random bet secs 18 & 13 Var 2° 8' W

Could not find cor to secs 13-24-18 & 19

S bet secs 19 & 24

51.388 Ft.

Int E & W  $\frac{1}{4}$  line 13 ft. E of  $\frac{1}{4}$  bet secs 19 & 24.

N corrected bet 19 & 24 Var 2° 17' E.

from W.C. to secs 24-25-30-19 described on page 35.

Enter river bottom hay marsh.

.0 Ft.

Wolf River E-bow

5.75 "

Wolf River

11.25 "

Leave River bottom for pasture.

17.75 "

Wolf River old bed, now backwater.

22.00 "

Leave old river bed for high land.

26.61 "

$\frac{1}{4}$  bet secs 19 & 24.

27.016 "

N corrected bet 19 & 24 from  $\frac{1}{4}$ , Var 2° W

.0 Ft.

W side of clearing

3.88 "

Leave clearing for dense spruce and balsam 3" to 6"

10.40 "

Leave spruce & balsam for 3" aspen.

13.88 "

Leave high land for swamp creek, bottom dense willow with scattering hay marshes.

25.694 "

Established cor to secs 18-19-13 & 24. Set and scribed cedar stake and drove 3' angle iron on N side of stake. No B.T. No timber near.

39

S random bet 13-18 from  $\frac{1}{4}$  see page 37.

N corrected bet secs 13 & 18. Cor described on page 37. Var 2° W.

16.00 Ft.

Swamp creek.

16.50 "

Leave creek bottom and enter jack pine flats.

Rep. scattering jack pine 3' to 6". few Norway.

25.694 "

$\frac{1}{4}$  bet secs 13 & 18.

Ogl B.T.'s Y pine 10 N  $1\frac{1}{2}$ ° E 214 lks. is burnt stump, some scribes show.

Ogl Y pine 18 S 85° W 225 lks. rotten and burnt stump no signs.

Recorded B.T. J. pine 14 N  $24\frac{1}{2}$ ° W 28 lks.

N on true line bet 13 & 18 Var 3° W

Wire fence on line.

13.768 Ft.

Fence W

27.537 "

Cor to secs 7 & 18 12 & 13

Ogl and recorded B.T.'s gone area burnt. Good wire fence N S & W from cor. Old stake burnt off. Distance all sandy J pine flats. Scattering reproduction.

41

13.34 Ft.  
26.59 "

N bet sec's 7 & 12 Var 2° E

Along wire fence on line from cor described on page 39.  
Canter of C.T.H. K & enter fair stand of 6" j.pine.  
 $\frac{1}{4}$  bet secs 7 & 12. Ogl B.T.'s gone.  
Recorded B.T.'s all gone but roots. Fence E on  $\frac{1}{4}$  line. Scribed fence post for  $\frac{1}{4}$ .

N bet 7 & 12 from  $\frac{1}{4}$  Var 2° E.

6.00 Ft.  
12.25 "  
13.215 "  
16.00 "  
22.29 "  
26.40 "

Wire fence bears 1° E of true line. Clearing E of line. Recent slashing W of line.  
Leave clearing for fair stand j. pine E of line 6"  
Enter swamp, rep scattering tam and spruce.  
6' to 20' high.  
Fence W and fence N on true line.  
Leave swamp for fair stand j-pine. Some mature.  
Enter Swamp Creek bottom, dense alder & willow.  
Cor to secs 6-7-1 & 12 and end of wire fence.  
Ogl tam 12 N 72° W 865 lks. Stub with center rotted out, no scribes, other Ogl gone. Made new B.T. Tam 6 S 30° E 238.7 ft.

42

26.089 Ft.

N on random bet secs 1 & 6 Var 2° E

Cor described on page 41.  
Int E & W  $\frac{1}{4}$  line 69 ft. W of  $\frac{1}{4}$  bet secs 1 & 6.  
Ogl B.T.'s Spr. pine 10 S 30° E 92 lks.  
(standing dead)  
Ogl Tam. 10 N 50° W 16 lks. down  
Set and scribed new cedar  $\frac{1}{4}$  post.  
New B.T. Fir 10 N 95° E 12.5 ft.

43

24.375 Ft.

N random bet 1 & 6 from  $\frac{1}{4}$  Var 0°

Int town line 53.9' ft E of cor to twps 34 & 35N  
Ranges 11 & 12 E.  
Ogl B.T.'s W pine 8 S 23° E 42 lks is stump on which scribes show.  
Ogl B.T.'s Spruce 12 N 61° W 17 lks, rotten stump  
Ogl B.T.'s W pine 8 S 50° E 49 lks, low stump, face rotted.  
Ogl B.T.'s W pine 10 N 60° E 33 lks, low stump, face rotted. Unrecorded BT Elm 14  
Put in and scribed new cedar stake in place of old scribed rotted stake.

N corrected bet 1 & 6 to  $\frac{1}{4}$  Var 1° 16' E.

1.25	Ft.	Swamp Creek, low banks
4.40	"	Swamp Creek, current sluggish
5.20	"	Swamp Creek
11.75	"	Swamp Creek
16.80	"	Leave creek bottom for 3" aspen
26.089	"	$\frac{1}{4}$ bet secs 1 & 6

N corrected bet 1 & 6 from  $\frac{1}{4}$  Var 1° 8' E.

.0	Ft.	Timber both sides of line
11.50	"	Open burning W of line.
		This half mile has a good stand of merchantable timber E of line, mostly balsam with a little spruce and white birch. Balsam is mature.
24.375	"	Twp cor.

E bet secs 6 & 31 Var 1° E on random

44

26.81	Ft.	Int N & S $\frac{1}{4}$ line 76.4' N of $\frac{1}{4}$ bet 6 & 31
		B.T. Ogl spruce pine 8 S 88° E 213 lks. is Y pine in good shape. stg. Ogl Y Bir gone. This $\frac{1}{4}$ falls in Swamp Creek, Original field notes call for the creek 50 lks W of $\frac{1}{4}$ . There are signs of the creek having been farther W. The old bed is now partly slough. Set and scribed new cedar stake.

E on random bet 6 & 31 from  $\frac{1}{4}$  Var 5° E

45

28.00	Ft.	Int N & S sec line 1.8' N of $\frac{31 32}{6 5}$
		Ogl Spruce 10 S 42 W 144 lks is spruce pine stub tree has fallen face rotten and partly burnt.
		Other B.T.'s gone. Old stake. Set and scribed new stake and drove angle iron on S. side.
		New B.T. W pine 14 N 82 $\frac{1}{2}$ ° W 150.6 ft.
		New B.T. Y pine 10 S 64 $\frac{1}{2}$ ° W 110.8 ft.

E corrected bet 6 & 31 Var 0° 45' W

.00	Ft.	Old burning
3.00	"	Good stand of common hardwood 8" to 12" S of line
		New slashing N of line.
14.00	"	Enter mixed hdw and aspen rep. 20 ft. high. few pine
18.25	"	Fire lane and enter balsam 4" to 10".
20.00	"	Swamp creek bottom, alder & willow.
26.67	"	Swamp creek
26.81	"	$\frac{1}{4}$ bet 6 & 31 in creek.



E corrected bet 6 & 31 from  $\frac{1}{4}$  Var  $5^{\circ} 4'$  E.

.07 Ft.  
1.60 "  
11.50 "  
28.00 "

E bank of Swamp creek. Fair current.  
Leave creek bottom for J.pine barrens. Rep.  
poor, recent burn.  
Enter swamp, mostly non-productive.  
Cor to secs 5-6-31-32.

E on random bet secs 5 & 32 Var  $5^{\circ}$  L.

46  
25.834 "  
51.668 "

Could not find  $\frac{1}{4}$  bet 5 & 32.  
Int N and S sec line 21.7' S of cor to  
secs 4-5-32 & 33. Old cruiser marks. Piece of  
old rotted stake, old blazes N.S.E & W of cor.  
No sign of any of the original B.T.'s. Set and  
scribed new cedar stake.  
New B.T.'s spruce 7 S  $71^{\circ}$  W 11.8 ft.  
New B.T.'s spruce 8 N  $75^{\circ}$  E 13.5 ft.

E corrected bet 5 & 32 Var  $5^{\circ} 21'$  E.

47  
25.834 Ft.

Cor in swamp.  
Established  $\frac{1}{4}$  bet 5 & 32. Set and scribed new  
tam stake and drove angle iron on S side.  
No trees near for B.T.s  
26.50 " Enter alder and willow  
37.00 " Enter dense spruce rep 16' high  
43.00 " Enter spruce and balsam, timber S of line,  
mostly open blowdown N of line.  
51.668 " Cor to secs 4-5-32 & 33. The E 3700 ft. of this  
mile is non productive swamp nearly open marsh  
extending  $\frac{1}{2}$  mile S of line. There are a few  
small J pine islands on and N of line recently  
burned with poor rep.

E on random bet 4 & 33 Var  $3^{\circ}$  E to  $\frac{1}{4}$

48  
26.77 Ft.

Int N & S  $\frac{1}{4}$  line 9 ft. N of  $\frac{1}{4}$  bet secs 4 & 33.  
Ogl B.T.s gone. Old cruiser marks. Unrecorded  
B.T.s Tam stump 10 S  $55^{\circ}$  E 16 ft.  
Cedar 14 S  $52\frac{1}{2}^{\circ}$  W 17 ft.  
Scribed tamarac stake in good shape. did not put  
in new stake.

49  
E on random bet 4 & 33 Var  $3^{\circ} 15'$  from  $\frac{1}{4}$

26.438 Ft.

Int N & S sec line. 11.2 ft. S of cor to  
secs 3-4-33 & 34. Flat stone with + on top.  
Could not find any original B.T.s, Unrecorded  
B.T. Norway stump N  $15^{\circ}$  W 40 ft., Set 3 " iron  
pipe on W side of stone.

E corrected bet 4 & 33. Var  $2^{\circ} 78'$  E to  $\frac{1}{4}$

.00	Ft.	Enter C.W.A. cleanup, thru standing timber
2.75	"	Enter pine island, mostly Norway.
6.00	"	Leave same.
13.40	"	Old slashing S of line, rep good spruce, balsam cedar 3" to 6".
26.77	"	$\frac{1}{4}$ bet 4 & 33

E corrected bet 4 & 33 from  $\frac{1}{4}$  Var  $3^{\circ}$  E.

.00	Ft.	Fence E nearly on line and used same for line, Did not set pickets.
		Burnt swamp S of line. Small spruce and balsam N of line.
13.18	"	$\frac{1}{8}$ stake 4 ft. S.
13.60	"	Started setting pickets
14.00	"	Leave swamp field 3 rds N of line, few scattering pine S of line.
18.00	"	Center of S.T.H. 55
18.26	"	27.5 ft. N to County line sign, 45.2 ft. S to center of Fire lane at Jct with S.T.H. 55.
22.50	"	Enter field
26.438	"	Cor to secs 3-4-33 & 34. Fence N, Fence S to fire lane.

S random bet 3 & 4 to  $\frac{1}{4}$  Var  $2^{\circ}$  W

24.30	Ft.	Int E & W $\frac{1}{4}$ line 2 ft. E of $\frac{1}{4}$ bet secs 3 & 4. Small stake in NE corner of old field, No B.T.s Set 3" iron pipe with cedar stake inside. Made + on E side of grey stone which bears N89 $^{\circ}$ W6' from cor.
-------	-----	---

N on random bet 3 & 4 Var  $4^{\circ}30'$  E.

27.49	Ft.	This cor conforms to the recorded County Field notes. Set new cedar stake. Roots of one orig B.T. Recorded B.T. Pine Stump 18 S $72^{\circ}$ W, 46 $\frac{3}{4}$ lks. Sugar 14 S 45 E $28\frac{1}{2}$ lks.
		Int E & W $\frac{1}{4}$ line 175 ft. W of $\frac{1}{4}$ bet 3 & 4. This cor described on page 50.

N corrected bet 3 & 4 to  $\frac{1}{4}$  Var  $56'$  E.

.00	Ft.	Fair Hwd timber E of line, new slashing W.
11.00	"	Leave Hwd for 3" aspen.
13.50	"	S.T.H. 55
20.00	"	Enter field line follows E edge of same. Did not set pickets in field.
27.49	"	$\frac{1}{4}$ bet 3 & 4, Surface level, light N slope.

S corrected bet 3 & 4 Var  $1^{\circ} 57'$  W.

.00 Ft.  
.18 "  
.53 "  
24.30 "

Fence S  
End of fence, turns W  
Center of fire lane.  
 $\frac{1}{4}$  bet 3 & 4. This  $\frac{1}{2}$  mile open pine barrens E  
of line and has scattering 6" white, Norway and  
jack pine between line and S.T.H. 55. Surface  
rolling, soil sandy.

S on true line bet secs 9 & 10 from corner  
described on page 51. Var  $45'$  W

.00 Ft.  
26.778 "

Line follows old wire fence.  
 $\frac{1}{4}$  bet 9 & 10, Set new cedar stake.  
Recorded B.T.s Maple 10 S  $14\frac{1}{2}$  E 38 lks-Hard maple.  
Recorded B.T.s Sugar 6 S 84 W 11 lks-Hard maple.  
with face markings rotted off.  
Recorded B.T.s Maple 10 N  $14\frac{1}{2}$  E  $37\frac{1}{2}$  lks is soft  
maple stump.  
This corner was established by a county  
surveyor midway bet sec corners. This  $\frac{1}{2}$  mile has  
scattering patches of No 2 Hwd balance 3 to 6"  
aspen. Surface level with light S slope near  
 $\frac{1}{4}$ . Original timber was mostly Hwd with few W pine.

S from  $\frac{1}{4}$  bet 9 & 10 Var  $45'$  W on true line.

.00 Ft.  
13.10 "  
13.389 "  
22.00 "  
26.778 "

Old fence S on line.  
Rep. 3" to 6" aspen mixed with No 2 Hwd.  
S end of old fence  
Center of C.T.H. K and enter 3" to 8" aspen.  
Enter swamp, alder with few conifers  
Cor to secs 9-10-15-16, Old stake, set and scribed  
new cedar stake. BTs Orig Tam Stump S  $3^{\circ}E$  9.8 ft.  
Recorded B.T. Tam stump S  $88^{\circ}W$  14 lks is rotten  
stump, no face or marks show.  
Recorded B.T. Tam stump 14 N  $37^{\circ}E$   $36\frac{1}{2}$  lks is rotten  
stump no face or marks show.  
New B.T. Cedar 8 N  $79^{\circ}W$  25.7 ft.  
Cor conforms to County Field notes. The distance  
between  $\frac{1}{4}$  and swamp has fairly heavy S slope.

S on true line bet 15 & 16 to  $\frac{1}{4}$  Var  $4^{\circ}W$  cor pp 53.

8.20 Ft.  
9.70 "  
13.261 "  
15.75 "  
22.75 "  
26.535 "

Stream 3' wide flows SW. Alder swamp  
Old RR grade bears N  $62^{\circ}W$   
 $\frac{1}{8}$  Stake. Set new stake. State land W of line  
Leave swamp. Rep balsam 3"-6" E of line  
Reenter same swamp.  
 $\frac{1}{4}$  bet 15 & 16 Two ogl BTs old stake down.  
Spruce stub 10 N  $42^{\circ}E$  10.8' ) Do not line with  
Spruce stp 10 S  $68^{\circ}W$  11. ' ) ogl field notes.  
New B.T. Cherry 8 S  $76^{\circ}E$  8.2'  
New B.T. Balsam 8 S  $40^{\circ}W$  11.5'  
Surface level. Set and scribed new  $\frac{1}{4}$  post.

55  
S bet 15 & 16 to  $\frac{1}{4}$  Var.

.00 Ft.  
13.50 "  
26.617 "

Highland with No 2 Hardwood and mixed conifers.  
Enter 3" to 6" aspen. Scrubby.  
Cor to secs 15-16-21-22. Rock at cor. Set and  
scribed new cedar stake.  
Ogl B.T.'s W pine stump S 20° W 39.6 scribes show  
Ogl B.T.'s W pine stump S 70° E 30.7 rotten  
Unrecorded B.T. Balsam stump 8 N 22° E 13.8'  
New BT's W pine 9 N 68° E 19.5'  
New BT's W Pine 16 N 65° W 51.5'  
Surface rolling.

56  
S bet 21 & 22 Var 3° E from cor described on pg.55.

26.895 Ft.

Int E & W  $\frac{1}{4}$  line 35.6 ft. W of  $\frac{1}{4}$  bet 21 & 22.

S corrected bet 21 & 22 Var 3° 45' E.

.00 Ft.  
4.00 "  
23.10 "  
24.00 "  
26.895 "

Enter good stand 6" aspen.  
Enter good stand 3" to 6" Hardwood. slashing.  
Old Tote road E & W  
Enter field  
Established  $\frac{1}{4}$  bet 21 & 22 in field. drove car  
axle in hole 1 ft. under surface and put broken  
glass in hole around axle.  
Made B.T. Scrubby W pine 14 S 84° E 172 ft.  
Unmarked W pine shade tree 16 N 40° E )  
Unmarked Y pine shade tree 12 N 24° E ) No  
Unmarked Maple shade tree 20 N 35° E )  
Unmarked Oak shade tree 18 N 1° 15' E ) Distance  
NW cor log burn S 17° 30' E )  
Surface rolling.

57  
N on random bet 21 & 22 Var 4° 19' E from  
cor to secs 21-22-27-28. This cor has scribed  
post painted white and flat iron rod on S. side  
1 Ogl B.T. N 8° E 38.2' is W. pine stump.  
Int E & W  $\frac{1}{4}$  line 26.1' W of  $\frac{1}{4}$  bet 21 & 22.

26.895 Ft.

N corrected bet 21 & 22 Var 3° 45' E

.00 Ft.  
14.23 "  
19.00 "  
26.895 "

Enter 12 ft. aspen with few conifers  
Wire fence E & W and enter grove.  
Leave grove for field.  
 $\frac{1}{4}$  bet 21 & 22. Surface level.

S bet secs 33 & 34 Var 4° E from cor to  
secs 27-28-33-34.

61  
28.346 Ft.

Set and scribed new cedar stake in 3 " pipe.  
This cor is in edge of clearing and has one  
jack pine B.T. S 50° E 25.2', others gone. Corner  
conforms to County Field notes. Ogl B.T.'s gone.  
Int E & W  $\frac{1}{4}$  line, 49.5' E of  $\frac{1}{4}$  bet 33 & 34.  
Ogl BT's gone. all cut for wood, set new stake.  
New BT Cedar 8 N 53 $\frac{1}{2}$ ° W 40.5'

S corrected bet 33 & 34 Var 30° E

.00 Ft.  
26.00 "

Enter pine barrens. No reproduction, few small patches of jack pine and aspen.  
Leave barrens for Pickerel Creek bottom. Rep 3" to 6" cedar and balsam, surface rough.

N on true line bet 33 & 34 to  $\frac{1}{4}$  Var 70° E.

.00 Ft.  
11.06 "  
14.00 "  
15.00 "  
20.50 "  
21.68 "

The cor to secs 3-4-33-34 is on W end of wire fence has plain stone and old scribed rotted stake down. No og1 BTs, drove 12" bolt in stump of old stake. New BT Jack pine 8S28°E 14.5' Rep. few aspen. Few inferior pine.  
Wire fence and enter W end of field.  
Leave field  
Enter swamp, few cedar tap, balsam.  
Pickerel Creek, low banks, mirey  
 $\frac{1}{4}$  bet 33 & 34. Surface rolling

62  
E bet secs 4 & 33 from  $\frac{1}{4}$  Var 40° E

10.25 Ft.  
13.40 "  
14.00 "  
15.00 "  
26.41 "

The  $\frac{1}{4}$  is in the center of N end of town road. Stone even with ground + on top. Set 7" cedar post 2 rd due W of  $\frac{1}{4}$  stone. Set 7" cedar post 2 rd. due E of  $\frac{1}{4}$  stone. Ogl B.T.'s gone.  
Unrecorded BTs Down W pine 10 E 27.5'  
Unrecorded B.T. Down W pine 12 N 36° W 17.4'  
Enter field  
Leave field for creek bottom  
Right bank Pickerel Creek  
Gain left bank and leave bottom.  
Cor to secs 3-4-33-34, described on page 61  
Surface rolling, soil light and sandy,  
Rep scattering aspen and Jack pine 2" to 6"

63  
W bet secs 4 & 33 from  $\frac{1}{4}$  Var 30° 30' E

.00 Ft.  
10.30 "  
18.50 "  
26.407 "

This cor described on page 62.  
Scattering patches 3" aspen and Jack pine  
Old Tote road. Has C.W.A. clean up on sides  
Enter swamp, rep fair, bal, cedar, spr 2" to 6"  
Cor to secs 4-5-32-33.  
Ogl BTs Cedar 12N27°W 8 lks, down & rotten off.  
Ogl BTs Cedar 12S36°W 29 lks, stub marks weathered  
Ogl BTs Cedar 12S15°E 7 lks, down, scribes cut off  
Ogl BTs Tam 11N56°E 24 lks, rotten stump & windfall.  
Unrecorded BT Tam stump 14S82 $\frac{1}{2}$ °E 16'  
Old scribed stake. Set and scribed new cedar stake.  
New BT Cedar 7S46 $\frac{1}{2}$ °E 16.6'; 6S89°W 29.5'  
Surface rolling, soil light and sandy.

64

E bet 5 & 32 to  $\frac{1}{4}$  Var 3° E from cor to  $\frac{31}{65}$ 

.25 Ft.

14.00 "

20.25 "

22.00 "

65 26.394 "

This corner is in intersection of angle formed by C.T.H. U, road runs S & W from cor. Fence N & E. Has stone with + on top.  
 B.T. Telephone pole 9 N 37° W 24.3'  
 B.T. Cedar Fence Post 8 N 78° E 25.2'  
 Fence on line runs E & W, J pine 3" to 6" N of line  
 Rep turns to 3 to 5" aspen with few pines  
 End of wire fence and enter Wolf River bottom.  
 Open hay marsh.

Wolf River  
 $\frac{1}{4}$  bet secs 5 & 32. This corner is in open hay marsh and has 2" iron pipe and lines with N & S fence on E side of field S of cor. Wolf River  $\frac{1}{4}$  rds N of cor. No trees near. Surface level. Soil sandy.

E bet 5 & 32 from  $\frac{1}{4}$  Var 2°30' E.

9.00 Ft.

13.25 "

25.00 "

26.425 "

Leave hay marsh for alder and willow swamp, had been tam. swamp and old flowage  
 Old  $\frac{1}{8}$  stake 25' N of line.  
 Enter cedar, bal, spruce rep 3 to 6"  
 Cor to secs 4-5-32-33 described on page 63.  
 Surface level, distance all swamp and open marsh.

W bet secs 6 & 31 from  $\frac{1}{4}$  Var 5° E

66

This  $\frac{1}{4}$  falls in the apex of the angle formed by using the center of C.T.H. U which runs N & E from this cor. The Langlade Co. Field notes call for a stone at this  $\frac{1}{4}$ . Mr. Powell, an old resident who helped place the stone says it was about 3 rds W of the  $\frac{1}{4}$  in the road. The  $\frac{1}{4}$  in the road was made in a later survey for Highway location and is not recorded. I could not find the stone  $\frac{1}{4}$ .

Enter farm yard.

Left bank of Hunting River, fair current, hard bottom  
 Gain right bank of Hunting River, and enter fair stand No 2 Hwd 6 to 10" with some conifers.

22.95 "

24.50 "

27.598 "

Right bank Hunting River, measured on ice.  
 Gain left bank and enter alder swamp. Had been cedar and tam timber killed by old flowage.  
 Cor to twps 33 & 34 N, Ranges 11 & 12 E,  
 Surface level. Soil sandy.

E bet 6 & 31 from  $\frac{1}{4}$  Var 5° E. This cor described on page 67.

26.43 Ft.

13 2 45

Along C.T.H. U, cor to secs 5-6-31-32 described on page 64, surface level, soil sandy, Cleared farm land on both sides of road.

## AINSWORTH UNIT SUBDIVISION

1936

34-12

N on random bet secs 31 & 32, Var 2°30' E to  $\frac{1}{4}$

27.82 Ft.

Cor to secs 5-6-31-32 described on page 64.  
Fell 30.2' E of  $\frac{1}{4}$  bet secs 31 & 32, See page 69  
for this  $\frac{1}{4}$ / Surface mostly level. Soil sandy  
Some old fields E of line balance used as pasture.  
Patches of Jack and Norway pine rep W. of line.  
Fair 0 to 6" few scattering Norway 6 to 10".

69

S on random bet secs 31 & 32 to  $\frac{1}{4}$  Var 2° E.

.00 Ft.

Rep. good aspen 0 to 4"

2.90 "

Enter swamp. Rep. good Cedar 0 to 3", few bal  
and spr. Some mature. Parts of swamp dense,  
good deeryard.

7.60 "

Leave swamp for good 6 to 12" Some bal and  
pine 0 to 6' W Bir dying.

12.50 "

Norway Pine grove on high bank of Wolf River.  
Good recreation spot.

16.365 "

Set up object.

16.55 "

Left bank of Wolf River, Highbank

19.70 "

Right bank of Wolf River, channel 150' N

Rep. Scattering jack pine and aspen 0 to 3",  
open spots.

20.531 "

Obtained distance across river, base 417.6, angle 45°

27.844 "

Fell 36.6' W of  $\frac{1}{4}$  bet secs 31 & 32. Recorded  
B.T. Y pine stump 10 1° 30' E 36 $\frac{1}{2}$  lks. is 1°30'W  
25.2' instead.

Recorded B.T. Y pine S87 $\frac{1}{2}$ ° E 17 $\frac{1}{2}$  lks, gone but roots  
Ogl B.T.'s gone area burnt hard.

Recorded stone 5 x 6 x 18 + on top for  $\frac{1}{4}$ . Set  
cedar post NW 1 rd. another SW 1 rd.

New B.T. Y Pine root N 52° E 8'. Surface level,  
Soil sandy, Used as pasture S of Wolf River.

70

E on random bet secs 30 & 31 Var 4°W to W.C. for  $\frac{1}{4}$

.00 Ft.

Old slashings, rep cedar fair 0 to 3"

3.00 "

Fair spr with few tam 0 to 3", peat swamp, sage  
brush undergrowth.

7.15 "

Leave swamp. Rep good aspen with few conifers 0-4"

11.42 "

Private road, Norway Point to C.T.H. U

11.66 "

Enter swamp. Same as at 300'.

13.80 "

Leave swamp for hills, rep good aspen, w, bir 0-3"

23.705 "

Offset S 32'. On as before.

25.35.8 "

Recorded W.C. for  $\frac{1}{4}$  bet secs 30 & 31.

71

Old stake scribed W.C. Set and scribed new cedar stake. Put stone around base. Recorded Hem BT's are rotten stumps, slight marks are left on one.

New BT Pine stump 16 N  $78\frac{1}{2}^{\circ}$  W - 11.1'

New BT W Bir 11 N  $88^{\circ}$  W - 10.1'

New BT S Elm 8 S  $60^{\circ}$  E - 37.7'

The recorded distance on this mile is 81.18 chains.

The govt dist is 79.20 ch. This makes the  $\frac{1}{4}$

116.1' E of the Witness Corner.  $\frac{1}{4}$  in Wolf River.

Surface  $W\frac{1}{2}$  level,  $E\frac{1}{2}$  hilly, soil light sandy loam

72

E on random bet secs 29 & 32 to  $\frac{1}{4}$  Var  $1^{\circ}$  15 E.

.0 Ft.

Ridges with scattering aspen 0 to 3", few pine seedlings.

1.27 "

Center of fire lane on Southerly bend.

3.92 "

Fire Lane NE

10.86 "

Old tota road Fire lane to Pearson

12.67 "

Peat Swamp, rep spr with few tam 0-3", sage brush undergrowth.

17.10 "

Leave swamp, Rep same as at 0.

23.10 "

Enter swamp Rep same as at 1267.

26.70 $\frac{1}{4}$  "

Leave swamp

26.70 $\frac{1}{4}$  "

Fell 5.9' S of  $\frac{1}{4}$  bet secs 29 & 32.

Plain stake set and scribed new cedar stake. Put stone around base. Stumps of both Ogl B.T.8

Ogl B Pine 12 S  $70^{\circ}$  E 15 lks is a Y Pine Stump

14 S  $64\frac{1}{2}^{\circ}$  E 10.3'

Ogl B. Pine 12N23 $^{\circ}$ W25 lks is 17.6' instead.

New BT Remarked base of Ogl. Y pine 14S64 $\frac{1}{2}^{\circ}$ E 10.3'

New Bearing + on flat grey stone even with surface S  $46\frac{1}{2}^{\circ}$  67.5'. Surface slightly rolling.

Soil sandy, most of distance repeatedly burned.

73

N on random bet secs 29 & 30 to  $\frac{1}{4}$  Var  $1^{\circ}$  45'E

74

Cor to secs 29-30-31-32 has a scribed stake painted white, set by J. M. Wilson. Low stump of Ogl Y pine 15N15 $^{\circ}$ E 35 lks was remarked by Wilson. Ogl marks cut off. Recorded BT Y pine 13S77 $\frac{1}{2}^{\circ}$ E 24 lks. o k is low stump no marks. rotten.

.0 Ft.

Highland ridges barren on top, rep fair 0-3" j.pine bal, aspen on swamp edges.

.63 "

Fire lane N & SE

5.00 "

Enter swamp, rep good, cedar spr, bal, 0-3". Some cedar suitable for small poles and posts.

75 13.267 "

Plain 1/8 stake 8.8' E.

26.416 "

Fell .3' E of  $\frac{1}{4}$  bet 29 & 30. Surface rolling, Soil sandy.



S on random bet secs 29-30 to  $\frac{1}{4}$  Var  $1^{\circ}30'$  E

.0 Ft.

Peat swamp, rep. poor Spr 0-4", few tam, sage brush undergrowth.

13.15 "

Creek 3 ft. wide flows SW

14.62 "

Leave swamp for E end of Point, Open with some fire cherry.

20.182 "

Fell 128.6 W of  $\frac{1}{4}$  bet 29 & 30.

Old stake burnt and rotten, set and scribed new cedar stake. Ogl BT's gone but few roots, area severely burnt. Unrecorded BT Tam  $6S3\frac{1}{2}OW17.7$  down Old cruiser marks and line blazes.

New bearings

+ on grey stone slab N  $65\frac{1}{2}^{\circ}$  W 27'

+ on grey round stone even with surface N  $56\frac{1}{2}^{\circ}$  E 31.7'. Surface level, soil sandy. There is a small  $1/8$  stake 1008' N of this  $\frac{1}{4}$  with E & W line blazes.

76

W on random bet secs 19 & 30 to  $\frac{1}{4}$  Var  $0^{\circ}$

.0 Ft.

Rep slow growing spr 0-4', peat swamp, sage brush.

11.00 "

Leave swamp, recent burn, rep 6' aspen.

12.60 "

N edge of swamp

16.00 "

Leave same, rep 6' aspen.

23.46 "

Center of fire lane

26.844 "

Fell 26.7' N of  $\frac{1}{4}$  bet secs 19 & 30. Old rotten scribed stake down, set and scribed new cedar stake with stone mound around base.

Ogl BT W pine 6 N  $45^{\circ}$  W 50 lks, gone but roots

Ogl BT Bir 6 S  $35^{\circ}$  E 56, down and rotten

Shows hole of old face, no marks.

Recorded BT Y pine 14 N  $70\frac{1}{2}^{\circ}$  E  $7\frac{1}{2}$  lks. o k

Recorded BT Y pine 11 S  $15^{\circ}$  E 31 lks. is  $17^{\circ}$

Recorded BT Y pine 11 N  $17^{\circ}$  W 14 lks.

All burnt stumps no marks show.

New bearings + on grey rock N  $13^{\circ}$  W 10.5'

+ on grey rock S  $60\frac{1}{2}^{\circ}$  E 24.4'

Surface slightly rolling, soil sandy, some openings

77

E on random bet secs 20 & 29

.0 Ft.

Peat swamp, rep spr. fair 0-4", sage brush undergrowth.

6.00 "

Rep cedar, bal 0-5" good, some mature

10.50 "

Lowland island, rep 3' bal.

17.90 "

Leave island, good cedar 3-9", good stand, small poles and posts.

20.85 "

Ridge rep. bal, few spr 0-6", some mature

26.00 "

Approx  $\frac{1}{4}$  78.8 N, Surface nearly level, soil sandy.

78

.25 Ft.  
4.35 "  
4.75 "  
27.075 "

S on random bet secs 19 & 20 from  $\frac{1}{4}$  Var 2°30' E

Leave swamp for ridge, rep fair, mostly balsam with few mixed pine 0-6"  
Truck Road E & W  
Enter swamp, rep. fair, slow growing spruce 0-4"  
Fell 34' E of cor to secs 19-20-29-30.  
Old scribed stake down and rotten, set and scribed new cedar stake, drove well point on S side of stake. Ogl Tam 8 S 25°W 25 lks, is S21°W 15.2' is rotten stump slab left marks show.  
Recorded BT Tam 8 51°W 26 lks is 48 $\frac{1}{2}$ °W.  
Recorded BT Spr 5 N 59°W 16 lks is stub o k  
Unrecorded BT Tam 4 S 46 $\frac{1}{2}$ ° E 26.5' stub  
Unrecorded BT Spr 6 N 43 $\frac{1}{2}$ ° E 19.1' stg.  
Other Ogl gone. Surface level, soil sandy, Swamp underlaid with peat, never had mature timber, rep. uneven, undergrowth, sage brush.

71

S on random bet secs 19 & 20 to  $\frac{1}{4}$ , Var 1° W

.0 Ft.  
10.00 "  
15.00 "  
23.75 "  
27.067 "

Lowland island, rep fair, aspen, J pine, bal, spr 0-3'  
Enter swamp, rep. fair, spr.0-6", few tam.  
Logging road E & W  
Spider creek 8 ft. wide, flows SW, rep spr 3-9"  
Fell 143.7' W of  $\frac{1}{4}$  bet secs 19 & 20.  
Old scribed stake down, set and scribed new cedar stake. Ogl BTs destroyed by logging road.  
Recorded BT Spr 8 N 45° E 15 lks is down and rotten, marks plain.  
New BT Tam stump 10 N 85° E 36.2'  
New BT Cherry 7 S 40 $\frac{1}{2}$ °W 37.5'  
Surface level, soil sandy, mostly old tam swamp, Considerable tam fuel wood.

W on random bet secs 18 & 19 Var 1° E to  $\frac{1}{4}$

80

.0 Ft.  
11.00 "  
13.392 "  
13.392 "  
26.28 "  
26.784 "

From a point 3.8S of cor to secs 17-18-19-20.  
Offset on rt  $\angle$  to random  
Rep fair spr 0-3 slow growing peat swamp, sage brush undergrowth.  
Leave swamp for J pine barrens, rep scattering J pine and aspen 0-3, few J and Norway pine 6-10'  
Center of N & S Hiway and offset S on 1°E 56.3'  
W along E & W Hiway Var 2°30' E.  
Leave Hiway and enter swamp.  
 $\frac{1}{4}$  bet secs 18 and 19. Small plain stake with RR angle iron and 1 $\frac{1}{4}$ " iron rod at side and few white bricks around base. Ogl BTs destroyed in making RR grade just W of cor.  
New BT J pine 4 N 14 $\frac{1}{2}$ ° E 36.6'  
New BT J pine 4 S 41° W 24.6'  
Made + on rock 2' high S 75° E 51.8'. Set and scribed new cedar stake put some irons at side and brick around base, added stone around base.  
Surface nearly level, soil light, sandy.

81

E on random bet secs 17 & 20 Var 40°E to  $\frac{1}{4}$

.0 Ft.  
8.00 "  
9.50 "  
11.50 "  
25.086 "

Lowland rep scattering J pine, bal, spr. 0-3"  
Enter swamp, no rep, alder willow.  
Spider creek 8 ft. wide, flows SW.  
Rep good, spr 0-6 with few bal 0-3.  
Fell 8.8' N of  $\frac{1}{4}$  bet secs 17 & 20. The 2 ogl  
BTs are tam instead of spr.  
Ogl Tam 12 N 29° E 15.6' instead of 25 lks.  
Ogl Tam 10 S 8° W 5.5' instead of 10 lks.  
New BT Soft Maple 8 N 55° E 23.4'  
New BT Spruce 12 S  $3\frac{1}{2}$ ° W 20.7'  
Old stake not marked set and scribed new cedar  
stake, surface level, soil sandy, good productive  
swamp. Patches of good Tam fuelwood.

82  
S on random bet secs 17 & 18 from  $\frac{1}{4}$  Var 2°W

.0 Ft.  
10.00 "  
26.027 "

Rep good bal few spr & cedar 3-6, some mature.  
Enter spruce swamp, rep fair 3-6.  
Fell 114.2 W of cor to secs 17-18-19-20.  
Small old scribed stake, set and scribed new  
cedar stake. 1 ogl BT Y pine 22 S 65° E 50 lks  
down face mostly burnt out. Other ogl gone.  
New BT Root of Ogl Y Pine S 62° E 32.9'  
New BT Tam stump N  $72\frac{1}{2}$ ° E 37.7'  
New BT J Pine 4 N 5° W 34.7'  
1 stone on S side of stake, surface level, soil  
sandy on few lowland island. Stations 0-10 good  
productive swamp; stations 10 to sec cor slow  
growing spruce with sage brush undergrowth.  
Few small J pine islands, rep scattering J pine  
and aspen 0-3.

83  
S on random bet secs 17 & 18 to  $\frac{1}{4}$  Var 1° 30' W

.0 Ft.  
9.00 "  
19.00 "  
26.726 "

Rep fair aspen with few mixed Hwd and conifers 3-5.  
Old truck road N NE  
Enter swamp, rep good, mostly bal, with few cedar  
and spruce. Scattering mature bal, cedar and spr.  
Some windfall.  
Fell 57.7 E of  $\frac{1}{4}$  bet secs 17 and 18. Old rotten  
scribed stake with stone around base down. Cor  
conforms to County Field notes. Ogl BTs rotten  
stumps gone but roots, set and scribed new cedar  
stake and put same stone around base.  
New BT Cedar 15 S  $81\frac{1}{2}$ ° E 84.6'  
New BT Cedar 9 S 54° E 73.5'  
Surface level, soil sandy, good productive swamp.

84

E on random bet secs 8 & 17 to  $\frac{1}{4}$  Var 2°30' E

Cor to secs 7-8-17-18. Ogl BT Y pine 20N32°E57lks is stump part of face shows no marks.

Ogl BT Y pine 20 S 56° E 60 lks is rotten stump.

Recorded BT W pine 12 S 51° E 22 lks is low stump part of face and marks show.

New BT Oak 6 S 63° E 33.6'

New BT Aspen 6 S 77° W 32.5'

New BT W Bir 4 N 31° E 36.9'

New BT Y pine 14 N 57° W 36.3'

Old scribed stake, set and scribed new cedar stake and made stone mound around base.

Rep W Bir aspen bal 0-4.

Enter swamp. Recent slashing cut close, few cedar and balsam N of line.

Lowland island. cut close, fire hazard.

Reenter same swamp

Lowland island

Reenter same swamp

Fell 7.5' S of  $\frac{1}{4}$  bet secs 8 & 17. Ogl Bir gone.

Ogl. Tam S 74 W is S72 E. Old hollow stub face shows marks gone.

Recorded BT W pine 36N 82° W 70 $\frac{1}{4}$  lks is pine stump marks plain.

Recorded BT Spruce 12 S 5° E 22 lks is down and nearly rotten marks show.

New BT W. Bir 10 N 57° E 5.5'

New BT Balsam 6 S 60° E 9.8

Old scribed stake about gone, set and scribed new cedar stake. Surface level, mostly swamp with lowland islands. Rep mostly scattering balsam 3-6 with few cedar and spr. This  $\frac{1}{2}$  mile except SW SW Sec 8 was slashed about a year ago. Much dry slash.

E on random bet secs 7 & 18 from  $\frac{1}{4}$  Var 2° E

This  $\frac{1}{4}$  has old rotten scribed stake down, set and scribed new cedar stake. Ogl BTs gone.

Recorded BT Pine Stump 24 S 4° W 71 lks.

Face about rotted away light shell left marks show.

Recorded BT Pine stump 14 S 36 $\frac{1}{2}$  W 110  $\frac{3}{4}$  lks.

Face and marks rotted away.

New BT W Bir 3 N 63° W 21.7'

New BT " Bir 4 N 30° E 8.2'

New BT Aspen 5 S 59 $\frac{1}{2}$  W 17.2'

Enter cultivated field

Leave same for pasture

Leave pasture for 3-6 aspen. Good stand few W bir and mixed Hwd.

Center of town road N & S, Maloney's to C.T.H. K.

Fence on approx line to  $\frac{1}{4}$

Fell 19' S of cor to secs 7-8-17-18. Surface level Mostly W slope, soil W $\frac{1}{2}$  sandy, E $\frac{1}{2}$  sandy loam.

85

.0	Ft.
4.50	"
18.00	"
20.00	"
23.00	"
25.90	"
26.318	"

86

87

.80	Ft.
3.35	"
9.50	"
13.164	"
13.40	"
26.355	"

88

.0 Ft.  
13.17 "  
13.438 "  
  
26.84 "

N on random bet secs 7 & 8 to  $\frac{1}{4}$  Var 30' E

For cor to secs 7-8-17-18, see page 84.

Old fence N to C.T.H. K on approx line.

Coast and Geodetic marker 49' W

Center of C.T.H. K, Swamp Creek School N of K and W of line. Offset 46.2' to old random line N Var 1° 30' E.

$\frac{1}{4}$  bet secs 7 & 8

Ogl W pine 15 S 25° W 40 lks is stump, scribes show but is 64.7' from cor.

Ogl Y Pine 12 N 20° E 50 lks is o k. This tree is down, face burnt.

Recorded BT Y pine 14 S 5° E 30 lks is rotten stump shell left, scribes show.

New BT Aspen 4 N 21 $\frac{1}{2}$ ° W 7'

New bearing + on rock S 18 $\frac{1}{2}$ ° E 20.9'

Old scribed stake down and charred, set and scribed new cedar stake, surface level, soil sandy loam

Rep fair, mostly aspen with few mixed Hwd 3-6.

Patches of clearing on SW SW of Sec 8, abandoned.

N on random bet secs 7 & 8 from  $\frac{1}{4}$  Var 1° W

.0 Ft.  
3.93 "  
4.50 "  
25.666 "

Fair aspen 0-3

Old truck road

Enter swamp, rep scattering tam, spr, bal 0-3.

Fell 40.1 E of cor to secs 5-6-7-8.

1 Ogl BT Tam 8 N 11° W 30 lks is live tree.

Other ogl gone.

New BT Tam 6 N 39° W 23.9'

New BT Tam 5 S 7° W 6.8'

New BT Tam 5 N 68 $\frac{1}{2}$ ° E 29'

Two small plain stakes too far E, set and scribed new cedar stake. Surface level, soil sandy,

This is old tam swamp, has about 6 cds dry tam fuelwood pr ac. Swamp 75% productive.

W on random bet secs 6 & 7 to  $\frac{1}{4}$  Var 2° 30' E

.0 Ft.  
17.75 "  
  
26.371 "

Rep fair tam 0-3 few spr.

Leave swamp, rep aspen 0-3 scattering J pine 3-6

Some fire cherry.

Fell 52.8 N of  $\frac{1}{4}$  bet secs 6 & 7. Old scribed stake down and rotten. Charred, set and scribed new cedar stake. Ogl BT Blk Pine 10 S 86° E 14 lks is 11.6' is stump BT mark left.

Ogl BT Blk Pine N 25° E 40 lks is 26' is low stump, BT mark left.

Unrecorded BT J pine stump 8 N 60 $\frac{1}{2}$ ° W 22.5'

New BT J. pine 7 N 88° E 38.5 & 7S 16° W 39.5'

Surface level, soil sandy, good tam fuel wood, 5 cds pr ac in swamp, few green tam 6-9". Swamp wet, swamp 75% productive.

89

90

91

.0 Ft.  
20.00 "  
26.864 "

E on random bet secs 5 & 8 to  $\frac{1}{4}$  Var 2° 30' E

Rep fair tam 0-3 few spr.  
Rep fair spr 0-3, few tam.  
Fell 79.4 S of  $\frac{1}{4}$  bet secs 5 & 8  
Old scribed stake rotten stg., set and scribed  
new cedar stake.  
1 og1 BT Tam 10 N 60° E 10 lks, marks plain, other  
og1 BT gone.  
Recorded BT Tam 12 S 15 $\frac{1}{2}$ ° W 27 lks is stub  
Recorded BT Tam 10 N 78° E 30 lks high stump  
Recorded BT Tam 10 N 32° E 20 lks high stump  
New BT Cedar 10 S 3° W 67.2'. Surface level,  
All swamp, scattering green tam 6-12", good  
tam fuel wood about 7 ods per ac. Stations  
0 to 14 are 75% productive.

N on random bet secs 5 & 6 to  $\frac{1}{4}$  Var 30' W

.0 Ft.  
5.00 "  
26.215 "

From a point 15.1 E of cor to secs 5-6-7-8.  
Offset rt  $\angle$  to random.  
Rep fair tam 0-3 few spr.  
Open swamp brs W & NE, old burning  
Fell 33.3 W of  $\frac{1}{4}$  bet secs 5 & 6. Old rotten  
stake down, set and scribed new cedar stake and  
drove 2" iron pipe on S side of stake.  
Ogl BT Tam 6 N 12° W 30 lks is low burnt, and  
rotten stump, slight trace of face.  
Other Ogl gone but roots.  
New BT Tam 4 S 61° E 34.6'  
New BT Tam 4 N 77° W 22'  
Surface level, all swamp. Stations 0 to 5 have  
5 ods tam fuelwood pr ac and scattering green  
tam 5-10". From station 5 to  $\frac{1}{4}$  is old burnt  
tam swamp with very little rep, 25% productive.

N on random bet secs 5 & 6 from  $\frac{1}{4}$  Var 30' W

24.999 Ft.

From a point 33.3 E of  $\frac{1}{4}$  Offset on rt  $\angle$  to random.  
Cor to secs 5-6-31-32. See page 45 for this cor.  
Surface level. All swamp except low 2 acre J pine  
island near Town Line which has good J pine rep  
0-3. Swamp nearly open marsh. Non productive  
Good cranberry swamp. Wet.

S on random bet secs 4 & 5 to  $\frac{1}{4}$  Var 1° W

.0 Ft.  
13.00 "  
25.743 "

See page 46 for cor to secs 4-5-32-33.  
Mature timber on State lands.  
5 acre patch of fair green tam 3-8" W of line  
Fell 153.9' W of  $\frac{1}{4}$  bet secs 4 & 5. Surface level  
All swamp. Some good merchantable Norway and W  
pine on islands near Town Line. Good merchantable

95

spr on same strip. N 30 rds. Balance old tam swamp, tam dead. Rep scattering spr and bal 2-9" with few cedar and tam. Some alder undergrowth Considerable tam fuelwood. This portion of swamp is about 50% productive.

N on random bet secs 4 & 5 to  $\frac{1}{4}$  Var 1° 30' E

13.283 Ft.  
17.75 "  
26.573 "

Old plain  $\frac{1}{8}$  post 59.2 E of random  
Bear Den 16 ft. W of this point, grown bear ran out.  
Fell 68.8' E of  $\frac{1}{4}$  bet secs 4 & 5.  
Ogl BT Tam 8 S 36° W is stub.  
Ogl BT Tam 10 N 5° E is stump.  
Marks plain in detail and conform to original notes for / and dist. No stake. Set and scribed new cedar stake.  
New BT Spr 6 S 77° W 25.6'; & 7 N 6° W 16.6'  
Surface level, all swamp, Timber E of line fair stand of spr, bal, cedar 3-9". Some merchantable on SW SW sec 4. The NW SW of sec 4 is State Land has limby spr and bal some cedar, scattering. W of line is old slashing tam and merch timber gone rep poor, bal spr, few cedar 0-3. Undergrowth alder.

E bet secs 4 & 9 to  $\frac{1}{4}$  Var 1° 30' E

96  
.0 Ft.  
5.00 "  
26.041 "

Along wire fence on approx line to  $\frac{1}{4}$ . Rep good Cedar, bal, spr. 3-8".  
Leave swamp rep aspen, w. bir 3-9" with few bal swamp brs E NE.  
 $\frac{1}{4}$  bet secs 4 & 9. Ogl BTs gone. This cor was reestablished from ogl by a county surveyor but his notes do not conform to this corner or the  $\frac{1}{4}$  a mile N. I think there was an error in recording.

Unrecorded BTs:

Low stump Y pine 16 N 23° E 24'  
Low stump Y Pine 14 N 58° E 35.4'  
New BT Y. Pine 14 S 62° E 40'  
New BT Aspen 5 N 42° W 13'

Cor had old scribed stake down, set and scribed new cedar stake. Surface slightly undulating, soil sandy, area had been mostly old pine land which has been burnt and reproduced to aspen and W Bir.

N bet secs 8 & 9 from  $\frac{1}{4}$  Var 2° E

97  
98  
.0 Ft.  
25.00 "  
26.42 "

Fence follows approx line to sec cor.  
Enter fair stand No 2 Hwd.  
Enter swamp rep good cedar bal 3-6.  
Old log road

26.734 Ft.

Cor to secs 4-5-8-9.

Ogl BT Cedar 20 S 58° E 8 lks is crotch and down. Marks weathered off. Ogl BT Tam 8 N 37° W 30 lks is gone but roots, found bottom end of old rotten stake, set and scribed new cedar stake.

New BT Cedar 8 N 57° W 27.3'

New BT Cedar 8 S 30° E 37'

New BT Spruce 8 S30° E 25.8'

Surface level, soil sandy loam. The No. 2 Hwd is 75% fuelwood; 25% merchantable. Rep fair, soft maple, hard maple, W Bir 3-9 with few hem and bal.

N bet secs 8 & 9 to  $\frac{1}{4}$  Var 1° W

Cor to secs 8-9-16-17. Ogl Spruce is rotten wind-fall. No marks. Ogl Bir is rotten stump. No marks.

Recorded BT Soft Maple 12 S 7° E 51 lks stg.

Recorded BT Spr Stump 16 N 82° E 33 lks.

(Unrecorded BT Soft Maple 12 N 74° W 17.2' stg.

(Unrecorded BT Soft Maple 10 N 84° W 19' stg.

(Unrecorded BT Soft Maple 14 S 51° E 17.5' stg.

(Face grown over, did not cut out.

Old scribed stake, set and scribed new cedar stake.

Old RR grade brs S 80° E.

Center of C.T.H. K and enter W edge of field fence on approx line to  $\frac{1}{4}$ .

Leave field

$\frac{1}{4}$  bet secs 8 & 9.

1 Ogl BT stg W Bir 12 S 43° E 8 lks.

Ogl Fir N 87° W 12 lks gone but roots.

Recorded BT Bir 14 N 18 $\frac{1}{2}$ ° W 36 $\frac{1}{4}$  is rotten stump,

No marks. Surface level, mostly lowland. Soil sandy loam very stoney. Timber No 2 Hwd. Mostly fuelwood. Rep. fair, Soft Maple, W. Bir Soft Elm 0-3, Bal, spr 3-6.

E on random bet secs 9 & 16 Var 4° E.

Scattering No 2 Hwd. Mostly fuelwood.

Wire fence N & S & enter field N & S

Wire fence brs NE & leave field for fair aspen 0-3 Undergrowth willow, low land.

Fell 37.2' N of  $\frac{1}{4}$  bet secs 9 & 16. Ogl Bir gone.

Ogl Cedar 10 N 36 W is stump. Face burnt.

Recorded BT W pine 24 S 20  $\frac{3}{4}$ ° E 40 lks ok shows marks.

New BT Cedar stump 10 S 13° W 17.6'

New BT Aspen 5 N 29° E 19.8'; New Bearing + on grey stone S 68 $\frac{1}{2}$ ° W 18.6'.

Old scribed cedar stake badly burnt. Set and scribed new cedar stake with stone mound. Surface level. Stoney. Soil mostly sandy loam. No. 2 Hwd mostly fuelwood W of field. Has fair mixed Hwd and conifer rep 3-6. Aspen lowlands approaching swamp E of field.

7.27 Ft.

13.315 "

18.00 "

26.63 "

.0 Ft.

9.00 "

23.00 "

26.393 "