CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

No evidence of any previous corner

Index No. 3 9-14

J 9-14

Description of corner evidence found:

Set meander corner on west shore of St. Johns Lake 22.0 ft. of waters edge. On a straight line between Section corner 8-9-16-17 and 1/4 corner between Section 9 & 16. Corner sets 224.02 ft. of section corner and 2351.46 ft. of 1/4 corner.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1" x 48" iron pipe for M.C. Marked NBTs

Tamarack 6" S65W 5.48 ft.
Tamarack 4" S62E 12.67 ft.

Scribed M.C. - B.T.

Dated at Rhiffelander, Wis., this 23rd day of November 19.83.

Signature Title Registered Land Surveyor Registration No. S1682

(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Forest I hereby certify that the within instrument was filed in this office for record on the 13th day of December 19.83.

(Register of Decis)

DOCUMENT NO. 124851