State of Wisconsin County of FOREST	ss. RESTORATION OF LOST ORIGINAL GOVERNMENT SURVEY CORNER.
19 64, I established	, do hereby certify that on the SEVENTEENTH day of SEPTEMBER the WITNESS CORNER TO THE CENTER QUARTER SECTION CORNER OF SECTION 14, E 13 EAST, Fourth Principal Meridian, as described here
History: There is no	record of this corner having ever been previously established.
At the point determined	t and accessories I established to perpetuate the location of this corner for the location of this corner for the location of the corner I emplaced a: CHREE FEET LONG, ONE INCH IN DIAMETER, WITH ALUMINUM CAP DENOTED AS,
"KIMBERLY CLARK CORP.	T34N C4 Section 14 WC - CORNER IS WEST 133.32 FEET - WC."
The pipe is witnessed by Elm 6 S 8 W 24 Elm 5 N 65 W 8	y: links. (Scribed C ¹ / ₄ S14 WC. BT). links. (Scribed C ¹ / ₄ S14 WC. BT).
Description as to how	corner was located: Two straight lines were run between the four previously established quarter section corners of this section. The intersection of the two lines, which is the position of the center quarter section corner, is in the lake at a point 38.99 chains south of the north quarter section corner, 38.24 chains north of the south quarter section corner, 39.22 chains west of the east quarter section corner and 39.05 chains east of the west quarter section corner. The witness corner to the center of the section was then set on the east—west quarter line on the east bank of the lake, 133.32 feet east of the center of the section.
O = Corner monument	89573
restored	JAN 12 3 Annalusan. Register of Deeds
	Resident witnesses
	Dated at Crandon , Wisconsin, this 12 day of Jan. , 19 65.
	Signature Registered Land Surveyor Registration No. 463
Surveyor's Seal	Officexefx I hereby certify that the within instrument was fidence within soft of Jan. 1965 December 12 day of Jan. 1965 December 1988 Of Xenax was x x x x x x x x x x x x x x x x x x x
	Signature Amns Seterson Title Notary Public