U S PUBLIC LAND SURVEY MONUMENT RECORD

(a) CORNER LOCATION EAST 1/4 CORNER OF SECTION 29 TOWNSHIP 34 NORTH RANGE 13 EAST OF THE 4TH PM TOWN OF NASHVILLE COUNTY OF FOREST

WISCRS - FOREST COUNTY N: 508,759.213 USft E: 840,624,658 USft Datum: NAD83 (2011) GNSS Method RTN - Direct GNSS Control WISCORS VRS



(b) HISTORY OF ORIGINAL CORNER ESTABLISHMENT

Original Surveyor: JAMES L. NOWLIN

Original Accessories: BIRCH 6 N18E 10LKS, CEDAR 7 N76W 24LKS

Date of Survey

Commenced: Completed:

OCTOBER 3, 1865

OCTOBER 18, 1865

See previous USPLS Monument Record **DOCUMENT NUMBER 189850**

INDEX NO. T-9 43413292000

(f)(g)(h) Description of monument found at this corner and if it was accepted, state all evidence (material, testimonial, occupational, plats, records, other monuments) used as a basis for accepting. If not accepted or if nothing was found, state evidence used as basis for establishing location. If re-established through lost corner proportionate methods, indicate all monuments, distances and directions used to establish. Indicate type of monument and sign post found or set.

JUNE 30, 1930 - J.L. MILLER "A SURVEYOR" PREPARES THE COOK AND BURNS PLAT ON PICKEREL LAKE, SAID PLAT CONSISTS OF ALL OF GOVERNMENT LOT 1, SECTION 29, TOWNSHIP 34 NORTH, RANGE 13 EAST, 4TH PRINCIPAL MERIDIAN, SOUTH OF THE QUARTER LINE.

JUNE 21, 1968 - SURVEYOR 00104 - ROBERT E. BANDOW PLACED OR FOUND A 1" DIAMETER IRON PIPE AT THE CORNER LOCATION WHILE PREPARING THE PLAT OF "FOUR SEASONS ESTATES FOREST COUNTY"


JANUARY 6, 2006 - SURVEYOR 1935 - DANIEL E. HIGGINBOTHAM FOUND AND ACCEPTED A 1" IRON PIPE AT THIS LOCATION AND PLACED A SMP NAIL AT THE SURFACE IN BT PATCH. HIGGINBOTHAM PREPARED A USPLS MONUMENT RECORD ON FILE AT FOREST COUNTY AS DOCUMENT NUMBER 189850.

SEPTEMBER 15, 2021 - I FOUND ALL OF HIGGINBOTHAM'S WITNESSES INTACT, I FOUND AN ASPHALT PATCH IN THE ROAD SURFACE, AND A MAGNETIC ATTRACTION AT THE LOCATION OF THE PATCH. I DID NOT FIND HIGGINBOTHAM'S

I DETERMINED THE SMP NAIL TO BE OBLITERATED REESTABLISHED ITS POSITION WITH A STANDARD MAG NAIL FROM HIGGINBOTHAM'S WITNESSES AS SHOWN BELOW.

The coordinate value shown is the average of two or more GPS observations at a markedly different time.


(c)(d)(e) Plan view of corner with ties to at least 4 witness monuments. If in disagreement with previously established corner, show the distances between the two corners and also indicate the ties to the disputed.





---189850


REGISTER'S OFFICE Forest County, Wi Received for record this. PASSEATOR ISCOIDS



U.S. PUBLIC LAND SURVEY MONUMENT RECORD

HISTORY OF ORIGINAL CORNER ESTABLISHMENT AND SUBSEQUENT RESTORATION AND DESCRIPTION OF ANY RECORD, MONUMENT OCCUPATIONAL, TESTIMONIAL OR OTHER EVIDENCE CONSIDERED:

HAND DUG IN ROAD AND FOUND A 1" PIPE 5" BELOW ROAD SURFACE. THIS LOCATION MATCHED THE LOCATION FROM PREVIOUS SURVEYS AND AGREED WITH THE LOCAL LANDOWNER'S TESTIMONY, ACCEPTED THIS LOCATION AND PLACED A "SMP NAIL" AT ROAD SURFACE IN BLACKTOP PATCH.



CORNER WAS: (CHECK ALL THAT APPLY)

- RESTORED THROUGH ACCEPTANCE OF AN OBLITERATED EVIDENCE LOCATION
- RESTORED THROUGH ACCEPTANCE OF A FOUND PERPETUATED LOCATION
- CONSIDERED A LOST CORNER AND REESTABLISHED THROUGH LOST CORNER PROPORTIONATE METHODS (INCLUDE A PLAN VIEW DRAWING SHOWING DISTANCES AND DIRECTIONS TO OTHER PUBLIC LAND SURVEY CORNERS USED FOR PROPORTIONING AND DETERMINING THE CORNER LOCATION)
- RESTORED OR REESTABLISHED IN A LOCATION THAT DIFFERS FROM A PREVIOUS RESTORATION OR REESTABLISHMENT (INCLUDE A PLAN MEW DRAWING AND INDICATE WHAT WAS SET AND/OR FOUND)
- ☐ CHECK IF THERE IS ADDITIONAL INFORMATION ON BACK

DESCRIBE THE MONUMENT AND ACCESSORIES USED TO PERPETUATE THE LOCATION OF THE CORNER. (INCLUDE A PLAN VIEW DRAWING AND INDICATE WHAT WAS SET AND/OR FOUND) ALSO INCLUDE FOUR TIES TO THE SECTION CORNER AND DESCRIPTION OF THE TIES.

