R9-7150-11 (9/1/66)

## CERTIFIED LAND CORNER RESTORATION

State of Wisconsin	Ss.		
County of Forest	<b>55.</b>		
Township 34 North	Range 14 Eas	Fou	day of October, 19.82, Section 19  Irth Principal Meridian, as described cessories as described hereon to per-
Description of original monum	ent and accessories and	subsequent restoratio	ns:
	eputy Surveyor, set	•	
			ar0m 40 71 (40 FLA)
Witne	ess trees (B.T's):	15" Sugar Maple 10" Yellow Birch	S7°E, 19 lks. (12.54') N30°W, 9 lks. (5.94')
Description of corner evidence	found:		
An extensive and intesting sites did not disclosed the original notes	ose any conclusive e	evidence, so I pro	at various possible oportioned against
Set 2" dia.x36" driv 1/4, S18/S19, T34N, Made and scribed bea (To nail in side of	R14E, S-1040, 1982 aring trees: 12" E 6" E tree)	Basswood N82 <sup>0</sup> W, 6 Basswood N5 <sup>0</sup> E, 6.2 Basswood S69 <sup>0</sup> E, 6 Basswood S69 <sup>0</sup> E, 6	.47' 21' .40'
			SURVE
	Resident witnesses	<del></del>	
Section 19	19.82 Robert Signature	H. Winat  L. H. Winat	Consin, this 6 day of October  Title Land Surveyor  eyor, or other duly authorized official)
	Surveyors Registrat	tion No. S-1040	······································
Corner monument restor	I hereby certify the on the 16th No. Restoration	t the within instrumeday of January Rage No. N-3	County of Forest, ent was filed in this office for record 1985, and was filed in Book of County Records.  Title Register of Deeds
Township 34 North, R	ange 14 East	Section 19 Ind	lex No