CERTIFIED LAND CORNER RESTORATION

State of Wisconsin			·
State of Wisconsin State	• •		.!
I Jean F. Resvick I found evidence of the Sou Township 34 North hereon; and that from this eviden	theast section , Range 15 East	corner of <u>Section</u> , Fourth Principal	Meridian, as described
petuate the original location of thi		ciit aiid accessories as di	escribed hereon to per-
Description of original monument	and accessories and subsequent	t restorations:	
Surveyed by James McBride in North between Sections 25 & 80.0 chains set post. Sugar, 8", N21°W, 35 lks. Hemlock, 10", N53°E, 7 lks. Sugar, 12", S57°E, 44 lks. Birch, 16", S9°W, 71 lks.	26		
Description of corner evidence fou	ınd:		
Iron pipe, 10 feet long in Old post lying alongside the Hemlock stump, 24", was 10" Birch stump, burned below good bearing tree, Hemlock	e pipe. when scribed, bears N53 ^c round level, bears S9 ^O W,	·	
Description of monument and access Replaced the iron pipe with filled with concrete, with S-802, From which the followaple, 15", N69°E, 31.44 fe	a 2 inch inside diameter a brass cap stamped, T341 wing bear:	r, galvanized pipe,	3 feet long,
Hemlock, 11", N18°W, 42.50		e de	00145.0000000000000000000000000000000000
Set a steel sign post, Nort			JEAN F. RESVICK RHINELANDER. WIS.
	Resident witnesses		
Sec. 23	Dated at Rhinelander 19.75 Signature Jean F. Resvice	Title Ca	
	(County Surveyor, Registered Surveyors Registration No	S-802 DOCU	MENT NUMBER 10'7006
Corner monument restored	I hereby certify that the within on the 30th day of A	in instrument was filed	in this office for record
	No. Page No. Signature Lugens		مو: u
Township34 North Range	Λ	(1 /1)	Y ₁