CERTIFIED LAND CORNER RESTORATION

State of Wisconsin		· · · · · · · · · · · · · · · · · · ·	
County of Forest	j.		
I Jean F. Resvick I found evidence of the south w	, do hereby certify that on the	17th day of section	October <u>19</u> 73,
Township 34 north	Range 16 east	, Fourth Principal	Meridian, as described
hereon; and that from this evider petuate the original location of the	,	and accessories as d	lescribed hereon to per-
December of seighbors of seighbors		-4	
Description of original monument	and accessories and subsequent re	storations:	
Surveyed by James McBride i North between sections 9 an	•	-	· •
Corner to Sections 3, 4, 9			•
Cedar, 12, N35W, 15 lks.		<u>-</u>	
Hemlock, 12, N48E, 23 lks. Cedar, 10, S39W, 5 lks.		•	
Cedar, 8, S50E, 23 lks.			
		•	
Description of corner evidence for	ana:		
Old post point Cedar snag. 14". S39°W. 5 1	ks., scribed		
Cedar snag, 14", S39°W, 5 1 Fallen cedar snag, S46°E, 2	3 lks., scribed	•	•
Hemlock stump, N48°E, 23 lk	.S. →	•	-
•	•		
		•	•
Description of monument and acc Replaced post point with a with concrete, with a brass	2 in. inside diam., galvani	zed pipe, 5 feet	long, filled
From which the followi	ng new bearing trees bear:		•
Balsam, 6 in., N37°E,	3.94 ft.		ABERBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBB
Balsam, 5 in., S67°E, Cedar, 4 in., N77°W, 8	8.80 ft. 3.20 ft.		S. S
Steel post, north, 1.5			JEAN F. RESVICK
			JEAN F. RESVICK
			RHINELANDEN, WIS.
		So. T	
•	•	B _Q	SUR NOBBERRE
	Resident witnesses		
	Dated at Rhinelander	XX7:	11 1 - 5 En A
		/ /	4 day of Fall.
Sec. 3	19.74. Signature Jean F. Resvick	out I and	J Chryson
	(County Surveyor, Registered Lan	•	
	Surveyors Registration NoS	802 DOCU	
	Office of Register of Deeds		NUMBER Forest
	I hereby certify that the within in	nstrument was filed	in this office for record
Corner monument restored	on the 5th day of	April 19 74	, and was filed in Book
	No	of County	Records.
• • • • • • • • • • • • • • • • • • •	Cimeta Table 1	TRAMAL TOUR RO	gister of Deeds

Township 34 north, Range 16 east