U.S. PUBLIC LAND SURVEY MONUMENT RECORD

Note: This form is intended and designed to fulfill all requirements of Wisconsin Administrative Code, Chapter A-E 7.08 U.S. Public Land Survey Monument Record (3)(a-i):

(a) CORNER LOCATION
Cor. of Secs. 3, 4, 33 & 34
Township 34 & 35 North
Range 12 East of the 4th P.M.
Town of Ainsworth/Nashville
County of Langlade/Forest

WISCRS - Langlade County N: 458,716.08 USft E: 663,556.49 USft WISCRS - Forest County N: 532,315.71 USft E: 814,916.45 USft Datum: NAD 83(2011)

GNSS Method: WISCORS RTN

SEC. 4
T34N R12E

(b) HISTORY OF ORIGINAL CORNER ESTABLISHMENT

Original Surveyor: Alfred Millard

Original Accessories:

Date of Survey

Commenced: August, 1857

Completed: August, 1857

Y. Pine 14" N5°E, 85 lks.
Y. Pine 15" N40°W, 48 lks.
W. Pine 18" S20°W, 58 lks.
Y. Pine 15" S55°E, 40 lks.

(b)(f)(g)(h) Description of monument found at this corner and if it was accepted, state all evidence (material, testimonial, occupational, plats, records, other monuments) used as a basis for accepting. If not accepted or if nothing was found, state evidence used as basis for establishing location. If re-established through lost corner proportionate methods, indicate all monuments, distances and directions used to establish. Indicate type of monument and sign post found or set.

This is a perpetuation of a previous USPLS Monument Record by Raymond J. Hallisy, RLS dated July 27, 1968 and filed in the office of the Langlade County Surveyor. A complete history of the corner can be found on the previous monument record. I accept the previous location as a true and faithful perpetuation or reestablishment of the original corner location and further perpetuate it as follows.


This is a perpetuation of a previous USPLS Monument Record by Thomas R. Arnott, RLS dated November 11, 1975 and filed in the office of the Forest County Register of Deeds. A complete history of the corner can be found on the previous monument record. I accept the previous location as a true and faithful perpetuation or reestablishment of the original corner location and further perpetuate it as follows.

To augment the record:

1932-1934: Survey notes by Charles W. Borth, Langlade County Surveyor Record #10317. "Flat stone with "+" on top. Could not find any original BT's. Unrecorded BT Norway stump N15 W, 40 ft. Set 3" iron pipe on W. side of stone."

October 22, 2016: I found and accepted a monument of unknown origin, a 2-1/2" diam. aluminum pipe with a 3-1/4" diam. Forest Co. aluminum cap projecting 6" above the ground surface. I set a DEEP-1 magnet adjacent to the monument. As described in the record, a 4" diam. brass-capped iron pipe bears West, 1.3 ft. The record birch and red pine at \$14'W are both gone. I found or established accessories as shown below. I set a white vinyl sign post bearing North, 0.7 ft.

(c)(d)(e) Plan view of corner with ties to at least 4 witness monuments. If in disagreement with previously established corner, show the distances between the two corners and also indicate the ties to the disputed.



FOREST COUNTY, WI
CORTNEY BRITTEN CLEEREMAN
REGISTER OF DEEDS
RECEIVED FOR RECORD

APR 2 7 2018

Time: 10: 10 A .M. Vol.: Corner Restoration Page Number: 2-13

WOODS ROAD (CL 55 ft. South)

(i) I, Jeffrey W. Austin, Professional Land Surveyor No. S-1885, hereby certify that the corner location on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

MAY 4, 2017



3512330000 (INDEX NO. A-13)

43512336666


State	of Wisconsin	•
	Tomografi	

I Thomas R. Arnott, do hereby certify that on the 22nd day
of September, 19.75, I found
evidence of the section
corner ofsections 3, 4, 33 & 34
Township. 34 & 35, North, Range
12E Fourth Principal Meridian,
as described hereon; and that from this evidence
I established a new monument and accessories
as described hereon to perpetuate the original
location of this corner.

} ss.

\mathbf{r}	• •		• ,	
iζ	PEIC	lent	witn	esses:
T	COLU		44 7 641	· · · · · · ·

Herbert Wagoner	
_	
	• • •
	· - ·



O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No.

History of original corner establishment:

Y. Pine	14	N5E	85 Lks.
Y. Pine	14 15 18	MLOW	48 Lks.
W. Pine	_	S20W	58 Lks.
Y. Pine	15	S55E	40 Lks.

Description of corner evidence found:

Langlade County W.C. 4" pipe filled with concrete and brass cap Brass Cap stating that corner is 1.3 feet E. to Corner Corner marked by wood post

Description of monument and accessories I established to perpetuate the original location of this corner.

Left concrete monument and wood post

Ties: to concrete monument:

Oak 8"	N21E	25.86 feet
R. Pinel6"		40.38 feet9 (BT found)
W. Birch 6	ⁿ N87W	6.73 feet (BT found)

THOMAS R.
ARNOTT
S-887

WIS.
SURVENIENTED TO 75

Dated at Crandon	, Wis., this	llth da	ay of Nov	zember 19.75	,)
Signature Remark. Muco	Title I	and Survey	70r	Registration No.S=887	
(County Surveyor, Re	gistered Land Surveyor	or other duly auth	norized official)		
Office of Register of Deeds, County	of FC	rest	, I	hereby certify that the within	jn
instrument was filed in this office for	r record on the	llth	day of NOVE	<u>əmber</u> , 19.75	2
at 40'clock PM. Light Esta (Register of				108212, mber.	