O = Corner	monument	restored.
------------	----------	-----------

CFRTIFIFD	IAND	CORNER	RESTORATION

Index No. Q - 1Z

History of original corner establishment:

No evidence of any previous corner.

Description of corner evidence found:

Corner established by subdivision of the SE 1/4. Location of SE 1/16 is S88-07-00E 1313.66 feet of SC 1/16 and S1-55-43W 1283.65 feet of EC 1/16.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1" iron pipe with 2" diameter alloy cap stamped:

Monument projects 12" above ground.

Marked NBT's:

Sugar 6" S81 E 7.73 feet

Sugar 6" N21 W 14.93 feet

Scribed 1/16-B.T.

S1682

T35N R13E

SE 1/16 S+21

SCPI - 1982

Dated at Rhivelander	, Wis., this	29th	day of	Novembe	r	19.82
Signature Den Berlen		Registered	•			on No. S1682
(County Surveyor, Register	ed Land Surve	yor, or other duly	authorized offici	al)	3	
Office of Register of Deeds, County of		Forest		,_I hereby	y certif	y that the within
Office of Register of Deeds, County of instrument was filed in this office for rec	ord on the	16th	day of	Februa	ry	ر <sub>19</sub> 85
at 10:30 o'clock A. M.  Lugen State (Register of Deed)						122915
(Register of Deed						`